CROO 51900

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)
Instructions for completing this report are on the last page of this form.

Croo 51900

WELL I.D. # L 20236
START CARD # 107460

(1) OWNER: Well Number _____
Name Earl + Shirley Hayton
Address 13960 Ochoco Hwy
City Prineville State OR Zip 97754

(2) TYPE OF WORK
[X] New Well [ ] Deepening [ ] Alteration (repair/recondition) [ ] Abandonment

(3) DRILL METHOD:
[ ] Rotary Air [ ] Rotary Mud [X] Cable [ ] Auger
[ ] Other _____

(4) PROPOSED USE:
[X] Domestic [ ] Community [ ] Industrial [ ] Irrigation
[ ] Thermal [ ] Injection [ ] Livestock [ ] Other _____

(5) BORE HOLE CONSTRUCTION:
Special Construction approval [ ] Yes [ ] No Depth of Completed Well 70 ft.
Explosives used [ ] Yes [ ] No Type _____ Amount _____

HOLE Diameter	From	To	SEAL Material	From	To	Sacks or pounds
10"	0	20	Bentonite	0	20	9 sacks
6"	20	70'				

How was seal placed: Method [ ] A [ ] B [ ] C [ ] D [ ] E
[X] Other Tremie Pipe
Backfill placed from _____ ft. to _____ ft. Material _____
Gravel placed from _____ ft. to _____ ft. Size of gravel _____

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	6	+1	70	250	[X]	[ ]	[X]	[ ]
					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
Liner:					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]

Final location of shoe(s) none

(7) PERFORATIONS/SCREENS:
[X] Perforations Method Cutting torch
[ ] Screens Type _____ Material _____

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
50	70	1/16	40	6"		[X]	[ ]
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]

(8) WELL TESTS: Minimum testing time is 1 hour
[ ] Pump [X] Bailer [ ] Air [ ] Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
20	0		1 hr.

Temperature of water 56° Depth Artesian Flow Found —
Was a water analysis done? [ ] Yes By whom —
Did any strata contain water not suitable for intended use? [ ] Too little
[ ] Salty [ ] Muddy [ ] Odor [ ] Colored [ ] Other —
Depth of strata: _____

(9) LOCATION OF WELL by legal description:
County CROOK Latitude _____ Longitude _____
Township 14 N or (S) Range 17 (E) or W. WM.
Section 24 NE 1/4 NE 1/4
Tax Lot 604 Lot _____ Block _____ Subdivision _____
Street Address of Well (or nearest address) 13960 NE Ochoco Hwy Prineville

(10) STATIC WATER LEVEL:
35 ft. below land surface. Date 4/19/02
Artesian pressure _____ lb. per square inch. Date _____

(11) WATER BEARING ZONES:
Depth at which water was first found 55'

From	To	Estimated Flow Rate	SWL
55'	65'	~~40~~ 20 GPM	35

(12) WELL LOG:
Ground Elevation _____

Material	From	To	SWL
Topsoil	0	1	
Brown Clay + Gravel	1	10	
Brown Clay	10	25	
Yellow Clay	25	55	
Gravel w/B	55	65	35
Tan Clay	65	70	35

RECEIVED
MAY 22 2002
WATER RESOURCES DEPT
SALEM, OREGON

RECEIVED
JUN 09 2006
WATER RESOURCES DEPT
SALEM, OREGON

Date started 4/17/02 Completed 4/19/02

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.
WWC Number _____
Signed [signature] Date 5/10/02

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.
WWC Number 444
Signed [signature] Date 5/10/02

ORIGINAL & FIRST COPY-WATER RESOURCES DEPARTMENT SECOND COPY-CONSTRUCTOR THIRD COPY-CUSTOMER