

Curr  
50197  
**RECEIVED**

L 13863

STATE OF OREGON  
WATER SUPPLY WELL REPORT

(START CARD) # 93922

(as required by ORS 537.765)  
WATER RESOURCES DEPT.

JUNE 1990 #

(1) OWNER: Dale Wilson  
Name: Burgundy Harvest Farms Inc  
Address: 32435 Libby Ck Rd  
City: Gold Beach State: OR Zip: 97244

(9) LOCATION OF WELL by legal description:  
County: Curry Latitude: Longitude:  
Township: 32 N or S Range: 15 E or W M.  
Section: 09 SW 1/4 SW 1/4  
Tax Lot: 1106 Lot: Block: Subdivision:  
Street Address of Well (or nearest address): Daey Rd

(2) TYPE OF WORK  
 New Well  Deepening  Alteration (repair/recondition)  Abandonment

(10) STATIC WATER LEVEL:  
15' ft. below land surface. Date: 6-18-97  
Artesian pressure: lb. per square inch. Date:

(3) DRILL METHOD:  
 Rotary Air  Rotary Mud  Cable  Auger  
 Other

(11) WATER BEARING ZONES:  
Depth at which water was first found: 18

(4) PROPOSED USE:  
 Domestic  Community  Industrial  Irrigation  
 Thermal  Injection  Livestock  Other

From	To	Estimated Flow Rate	SWL
18	40	12 gpm	15

(5) BORE HOLE CONSTRUCTION:  
Special Construction approval  Yes  No Depth of Completed Well: 40 ft.  
Explosives used  Yes  No Type: Amount:

HOLE			SEAL			Sacks or pounds
Diameter	From	To	Material	From	To	
9	0	18	Bent	18	0	12 1/4
7 1/2	18	40				

How was seal placed: Method  A  B  C  D  E  
 Other  
Backfill placed from ft. to ft. Material:  
Gravel placed from ft. to ft. Size of gravel:

(12) WELL LOG:  
Ground Elevation:

Casing:	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
	4 1/2	2	22	5/16				

  

Liner:	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded

Material	From	To	SWL
Brown clay	0	2	
Brown sand + clay mixed	2	18	
Brown sand + gravel	18	40	15

Final location of shoe(s):

(7) PERFORATIONS/SCREENS:

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
40	20	0.010		4 1/2	4 1/2		

Date started: 6-17-97 Completed: 6-18-97

(8) WELL TESTS: Minimum testing time is 1 hour  
 Pump  Bailer  Air  Flowing Artesian  
Yield gal/min: 12 Drawdown: Drill stem at: 40 Time: 1 hr.

(unbonded) Water Well Constructor Certification:  
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

Temperature of water: 52° Depth Artesian Flow Found:  
Was a water analysis done?  Yes By whom:  
Did any strata contain water not suitable for intended use?  Too little  
 Salty  Muddy  Odor  Colored  Other:  
Depth of strata:

WVC Number:  
Signed: Date:  
(bonded) Water Well Constructor Certification:  
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.  
WVC Number: 1381  
Signed: Date: 7-9-97