STATE OF OREGON
WATER WELL REPORT
(as required by ORS 537.765)

DESC 1469

RECEIVED MAR 18 1993 WATER RESOURCES DEPT. SALEM, OREGON

14S/13E/36d

(START CARD) # 46642

(1) OWNER: Well Number 9301
Name Raymond Fontaine
Address 3008 S.W. Glacier Ave.
City Redmond, State Or. Zip 97756

(2) TYPE OF WORK:
[X] New Well [ ] Deepen [ ] Recondition [ ] Abandon

(3) DRILL METHOD:
[X] Rotary Air [ ] Rotary Mud [ ] Cable
[ ] Other

(4) PROPOSED USE:
[X] Domestic [ ] Community [ ] Industrial [ ] Irrigation
[ ] Thermal [ ] Injection [ ] Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval [ ] Yes [X] No Depth of Completed Well 300 ft.
Explosives used [ ] Yes [X] No Type Amount

HOLE Diameter	From	To	SEAL Material	From	To	Amount sacks or pounds
14"	0	18½	Bentonite	0	18½	22 Sks.
8"	18½	300				

How was seal placed: Method [ ] A [ ] B [ ] C [ ] D [ ] E
[ ] Other Poured Dry
Backfill placed from ft. to ft. Material
Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	8"	+1½	-18½	.250	[x]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
Liner:	Recomended, But				[ ]	[ ]	[ ]	[ ]
	Not Installed				[ ]	[ ]	[ ]	[ ]

Final location of shoe(s)

(7) PERFORATIONS/SCREENS:
[ ] Perforations Method
[ ] Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]

(8) WELL TESTS: Minimum testing time is 1 hour
[X] Pump [ ] Bailer [ ] Air [ ] Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
16	5 Ft.		1 hr.

Temperature of Water 51° Depth Artesian Flow Found
Was a water analysis done? [X] Yes By whom Century West
Did any strata contain water not suitable for intended use? [ ] Too little
[ ] Salty [ ] Muddy [ ] Odor [ ] Colored [ ] Other No
Depth of strata:

(9) LOCATION OF WELL by legal description:
County Deschutes Latitude Longitude
Township 14S N or S. Range 13E E or W. WM.
Section 36 S/W ¼ S/E ¼
Tax Lot 2600 Lot Block Subdivision
Street Address of Well (or nearest address) 3875 N.E. Upas REdmond, Or. 97756

(10) STATIC WATER LEVEL:
232 ft. below land surface. Date 1/23/93
Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:
Depth at which water was first found 233

From	To	Estimated Flow Rate	SWL
233	300	No REturn	232

(12) WELL LOG:
Ground elevation

Material	From	To	SWL
Brn. Soil & Bldrs	0	5	
Gray Basalt	5	52	
Crevice No Return	52	85	
Brn. Conglomerate	85	131	
Gray Basalt	131	146	
Crevice No Return	146	262	232
Cinder Conglomerate	262	300	

RECEIVED FEB 18 1993 WATER RESOURCES DEPT SALEM, OREGON

Date started 1/6/93 Completed 1/22/93

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.

WWC Number
Signed Date

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.

WWC Number 665
Signed William D. Williams Date 2/16/93

ORIGINAL & FIRST COPY - WATER RESOURCES DEPARTMENT SECOND COPY - CONSTRUCTOR THIRD COPY - CUSTOMER 9809C 10/91