

RECEIVED

531215g/12E-14de  
well log #2

SEP 16 1988

STATE OF OREGON  
WATER WELL REPORT  
(as required by ORS 537.785)

DESC  
3578

(1) OWNER: Owner's Well Number: 6  
Name Eagle Crest Resort  
Address 1522 Cline Falls Rd.  
City Redmond State OR Zip 97756

(2) TYPE OF WORK:  
 New Well  Deepen  Recondition  Abandon

(3) DRILL METHOD:  
 Rotary Air  Rotary Mud  Cable  Other

(4) PROPOSED USE:  
 Domestic  Community  Industrial  Irrigation  
 Thermal  Injection  Other

(5) BORE HOLE CONSTRUCTION:  
Depth of Completed Well \_\_\_\_\_ ft.  
Special Standards date of approval \_\_\_\_\_  
HOLE SEAL Amount  
Diameter From To Material From To sacks or pounds  
How was seal placed? Method  A  B  C  D  E  
 Other  
Backfill placed from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Material \_\_\_\_\_  
Gravel placed from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Size of gravel \_\_\_\_\_

(6) CASING/LINER:  
Diameter From To Gauge Steel Plastic Welded Threaded  
Casing: \_\_\_\_\_  
Liner: 12" +2 -225 .188      
Final location of shoe(s) \_\_\_\_\_

(7) PERFORATIONS/SCREENS:  
 Perforations Method \_\_\_\_\_  
 Screens Type Cooke Material \_\_\_\_\_  
From To Slot size Number Diameter Tele/pipe size Casing Liner  
-220 -275 20 \_\_\_\_\_ 12" Tele

(8) WELL TESTS: Minimum testing time is 1 hour  
 Pump  Bailer  Air  Flowing Artesian  
Yield gal/min Pumping level Drill stem at Time 1/4 hr  
700 270 ft. \_\_\_\_\_ 24 hr.  
A & H Pump Services  
Temperature of water \_\_\_\_\_ Depth Artesian Flow Found \_\_\_\_\_  
Was a water analysis done?  Yes By whom \_\_\_\_\_  
Did any strata contain water not suitable for intended use?  Too little  
 Salty  Muddy  Odor  Colored  Other \_\_\_\_\_  
Depth of strata: \_\_\_\_\_

(9) LOCATION OF WELL by legal description:  
County Deschutes Oregon Latitude \_\_\_\_\_ Longitude \_\_\_\_\_  
Township 15S N or S, Range 12E E or W, WM.  
Section 14 SW 1/4 SE 1/4  
Tax Lot \_\_\_\_\_ Lot \_\_\_\_\_ Block \_\_\_\_\_ Subdivision \_\_\_\_\_  
Street Address of Well (or nearest address) \_\_\_\_\_

(10) STATIC WATER LEVEL:  
226 ft. below land surface. Date 8-15-88  
Artesian pressure \_\_\_\_\_ lb. per square inch. Date \_\_\_\_\_

(11) WELL LOG: Ground elevation \_\_\_\_\_  
Material From To WB? SWL  
install casing and sandscreen  
see well log #1 for Eagle Crest Resort  
start card # 5310  
Date started 8-29-88 Completed 8-31-88

(unbonded) Water Well Constructor Certification:  
I constructed this well in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.  
Signed \_\_\_\_\_ Date \_\_\_\_\_

(bonded) Water Well Constructor Certification:  
I accept responsibility for construction of this well and its compliance with all Oregon water well standards. This report is true to the best of my knowledge and belief.  
Signed Larry Crawford Date 9-9-88  
Company Crawford Well Drilling Co. Job No. \_\_\_\_\_