

RECEIVED

DESC 3688

153/13E-3dd

STATE OF OREGON WATER WELL REPORT (as required by ORS 537.765)

OCT 27 1986

(1) OWNER: Orvail Buckner WATER RESOURCES DEPT. SALEM, OREGON

(2) TYPE OF WORK: [X] New Well [] Deepen [] Recondition [] Abandon

(3) DRILL METHOD: [X] Rotary Air [] Rotary Mud [] Cable [] Other

(4) PROPOSED USE: [X] Domestic [] Community [] Industrial [] Irrigation [] Thermal [] Injection [] Other

(5) BORE HOLE CONSTRUCTION: Depth of Completed Well 447 ft. Special Standards date of approval

Table with columns: HOLE (Diameter, From, To), SEAL (Material, From, To), Amount (sacks or pounds)

How was seal placed? Method [] A [] B [] C [] D [] E [] Other Cement Grout

(6) CASING/LINER: Table with columns: Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded

Location of shoe(s)

(7) PERFORATIONS/SCREENS: Table with columns: From, To, Slot size, Number, Diameter, Tele/pipe size, Casing, Liner

(8) WELL TESTS: Minimum testing time is 1 hour. Pump [] Bailer [X] Air [] Flowing Artesian []

Temperature of water 50* Depth Artesian Flow Found Was a water analysis done? [] Yes [X] No By whom none

(9) LOCATION OF WELL by legal description: Deschutes County Latitude Longitude Township 15S N or S, Range 13E E or W, WM. Section 31 SE 1/4 SE 1/4

(10) STATIC WATER LEVEL: 330 ft. below land surface. Date 10-6-86

(11) WELL LOG: Table with columns: Material, From, To, WB?, SWL

Date started 10-2-86 Completed 10-6-86

(unbonded) Water Well Constructor Certification: I constructed this well in compliance with Oregon well construction standards...

(bonded) Water Well Constructor Certification: I accept responsibility for construction of this well and its compliance with all Oregon water well standards...

Company Orvail Buckner Well Drill'g, Inc.