

WATER SUPPLY WELL REPORT

DESC 51803

Received Date 8/5/1998

(as required by ORS 537.765)

Well ID # L 4582

Instructions for completing this report are on the last page of this form.

Start Card # 115429

(1) OWNER Well Number Name HAP TAYLOR & SON Street P.O. BOX 83 City BEND State OR Zip 97702	(9) LOCATION OF HOLE By legal description County Deschutes Latitude Longitude Township 15.00 S Range 9.00 E Subdivision Tax lot 300 Lot Block Section 3 NW 1/4 1/4 Street Address of Well (or nearest address) 5 MILES S OF SISTERS OFF MCKENZI HW MAP with location indentified must be attached																												
(2) TYPE OF WORK ☐ New ☐ Alter (Recondition) ☐ Alter (Repair) ☒ Deepening ☐ Abandonment	(10) STATIC WATER LEVEL 425.0 Ft. below land surface. Date 8/5/1998 Artesian Pressure lb/sq. in. Date																												
(3) DRILL METHOD ☒ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger Other	(11) WATER BEARING ZONES Depth at which water was first found 561 ft. <table border="1" style="width: 100%; border-collapse: collapse;"><thead><tr><th>From</th><th>To</th><th>Est. Flow Rate</th><th>SWL</th></tr></thead><tbody><tr><td>561</td><td>576</td><td>50</td><td>425</td></tr></tbody></table>	From	To	Est. Flow Rate	SWL	561	576	50	425																				
From	To	Est. Flow Rate	SWL																										
561	576	50	425																										
(4) PROPOSED USE ☐ Domestic ☐ Community ☐ Industrial ☒ Irrigation ☐ Injection ☐ Livestock ☐ Thermal Other	(12) WELL LOG Ground Elevation ft. <table border="1" style="width: 100%; border-collapse: collapse;"><thead><tr><th>Material</th><th>From</th><th>To</th><th>SWL</th></tr></thead><tbody><tr><td>BASALT GRAY</td><td>401</td><td>408</td><td></td></tr><tr><td>LAVA RED/PUMICE LAYERS</td><td>408</td><td>473</td><td></td></tr><tr><td>LAVA RED</td><td>473</td><td>502</td><td></td></tr><tr><td>LAVA GRAY</td><td>502</td><td>561</td><td></td></tr><tr><td>CINDERS</td><td>561</td><td>576</td><td>425</td></tr><tr><td>LAVA RED</td><td>576</td><td>595</td><td></td></tr></tbody></table>	Material	From	To	SWL	BASALT GRAY	401	408		LAVA RED/PUMICE LAYERS	408	473		LAVA RED	473	502		LAVA GRAY	502	561		CINDERS	561	576	425	LAVA RED	576	595	
Material	From	To	SWL																										
BASALT GRAY	401	408																											
LAVA RED/PUMICE LAYERS	408	473																											
LAVA RED	473	502																											
LAVA GRAY	502	561																											
CINDERS	561	576	425																										
LAVA RED	576	595																											
(5) BORE HOLE CONSTRUCTION Special Standards ☐ Depth of completed well 595 ft. Explosives Used ☐ Amount Type <table border="1" style="width: 100%; border-collapse: collapse;"><thead><tr><th>Diameter</th><th>From</th><th>To</th></tr></thead><tbody><tr><td>8.00</td><td>401.00</td><td>595</td></tr></tbody></table> How as seal placed: Method Other DID NOT DISTURB Backfill placed from ft. TO ft. Material Filter pack from ft. TO ft. Size in.	Diameter	From	To	8.00	401.00	595	(6) CASING/LINER																						
Diameter	From	To																											
8.00	401.00	595																											
(7) PERFORATION/SCREENS ☐ Perforation: Method ☐ Screens Type Material	(8) WELL TESTS (Minimum testing time is 1 hour) Type of Test Yield Units Drawdown Stem at Duration Air 50.0 G 535 2.0 Temperature of water 54 °F/C Depth artesian flow found ft. Was water analysis done? ☐ By Whom? Did any strata contain water not suitable for intended use? ☐ Too Little ☐ Salty ☐ Muddy ☐ Odor ☐ Colored Other Depth of strata ft.																												
(8) WELL TESTS (Minimum testing time is 1 hour) (unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to the best knowledge and belief. WWC Number Signed By (bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief. WWC Number 758 Signed By THOMAS R PECK D-3 WELL DRILLING																													