STATE OF OREGON					
WATER SUPPLY WELL REPORT	DESC 52003			10/31/1998	
(as required by ORS 537.765)			Well ID Tag #		
Instructions for completing this report are on the last page of this form	Start Card # 115415				
(1) OWNER Well Number		(9) LOCATION OF HOLE By legal description			
Name BILL KELLEHER		County Deschutes Latitude Longitude			
• • • • • • • • • • • • • • • • • • • •		Township 14.00	S Range 10.00	E Sul	bdivision
		Tax lot 6500	Lot Block		
City SISTERS State OR Zip 97759			NW 1/4 NW 1/4		
(2) TYPE OF WORK		Street Address of We	ll (or nearest address)		
New Alter (Recondition) Alter (Repair) Deepening Abandonment		LOT 2 BLK 1: IN	IDIAN FORD MEAD	OWS: STAR	R RANCH
		MAP with location in	dentified must be attach	ed	
(3) DRILL METHOD		(10) STATIC V	NATER LEVEL		
🖂 Rotary Air 🔄 Rotary Mud 📄 Cable 📄 Auger		138.0 Ft. below land surface. Date 10/27/1998			
Other		Dete			
				n. Date	
(4) PROPOSED USE		BEARING ZONES	•		
Domestic Community Industrial Irrigation Injection		Depth at which w	vater was first found 37		
		37		Rate SWL	
(5) BORE HOLE CONSTRUCTION				I	1
Special Standards Depth of completed well 386 1	ft.				
Explosives Used Amount Type		(12) WELL LO			t
Diameter From To				From	To SWL
6.00300.00 386		LAVA GR	AY BROWN	300	
		SANDSTC		356	
How as seal placed: Method Other DID NOT DISTURB					
Backfill placed from ft. TO ft. Material					
Filter pack from ft. TO ft. Size in	n				
		-			
(6) CASING/LINER					
		-			
(7) PERFORATION/SCREENS					
Perforation₃ Method					
Screens Type Material					
		4			
(8) WELL TESTS (Minimum testing time is 1 hour	r)	Date started	10/27/1998	Completed 1	0/27/1998
Type Yield Units Drawdown Stem at Duration Air 75.0 G 380 1.0		(unbonded) Water We	Il Constructor Certification:	•	
		I certify that the work I performed on the construction, alteration, or abandonment			
		of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to the best knowledge and belief.			
			כם מטטיפ מופ נוטפ נט נחפ ט	est knowledge and	
Temperature of water 54 °F/C Depth artesian flow found	ft.	Signed By (bonded) Water Wel	Constructor Codifications	MANO NUME	or
Was water analysis done?			I Constructor Certification: for the construction, altera	WWC Numb ation, or abandonm	
By Whom?		performed on this well	during the construction dat	es reported above	. All work
Did any strata contain water not suitable for intended use? Too Little	e Salty		ime is in compliance with C e best of my knowledge ar	-	iction standards.
Muddy Odor Colored Other			,	WWC Number	r 758
Depth of strata ft.		Signed By THOMA	SRPECK D-3	3 WELL DRILLI	NG