

DESC 5714 185/15E/16dd
(Start Card)# 9622

(9) LOCATION OF WELL by legal description:
County Des. Latitude _____ Longitude _____
Township 18 N or S, Range 13 E or W, WM.
Section 16 SE $\frac{1}{4}$ SE $\frac{1}{4}$
Tax Lot 2100 Lot _____ Block _____ Subdivision _____
Street Address of Well (or nearest address) 23130 Richard Rd.

(10) STATIC WATER LEVEL:

782 ft. below land surface. Date 1/11/90
Artesian pressure _____ lb. per square inch. Date _____

(11) WATER BEARING ZONES:

Depth at which water was first found 782

From	To	Estimated Flow Rate	SWL
782	842	25	782

(12) WELL LOG:

Ground elevation

[illegible]

Date started 7/20/89 Completed 1/12/90

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.

Signed John Smith WWC Number 1371
Date 2/2/90

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.

Signed 1/14/90 J. O. H. [Signature] Date 2/2/90

PY - CONSTRUCTOR PINK COPY - CUSTOMER

9809C 10/86

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	8"	+1	19	250	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:	6"				☒	☐	☒	☐
					☐	☐	☐	☐

Final location of shoe(s)

PERFORATIONS/SCREENS:

☒ Perforations Method Factory
☐ Screens Type _____ Material _____

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
785	825	1/8x3	200	6"	pipe	☐	☒
						☐	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour

☒ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
25	0		1 hr.

Temperature of water 56 Depth Artesian Flow Found

Was a water analysis done? ☐ Yes By whom _____

Did any strata contain water not suitable for intended use? ☐ Too little

☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other _____

Depth of strata: _____