RECEIVED
DESC 57772
JAN 03 2007
WATER RESOURCES DEPT
SALEM, OREGON

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)

WELL I.D. # L _____

START CARD # 180712

Instructions for completing this report are on the last page of this form.

(1) LAND OWNER Well Number _____
Name Virginia Redick
Address 60095 Itopi Rd.
City Bend, State OR Zip 97702

(2) TYPE OF WORK ☐ New Well
☐ Deepening ☐ Alteration (repair/recondition) ☒ Abandonment ☐ Conversion

(3) DRILL METHOD
☐ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger ☐ Cable Mud
☐ Other _____

(4) PROPOSED USE
☐ Domestic ☐ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☐ Livestock ☐ Other _____

(5) BORE HOLE CONSTRUCTION Special Construction: ☐ Yes ☐ No
Depth of Completed Well _____ ft.
Explosives used: ☐ Yes ☐ No Type _____ Amount _____

BORE HOLE Diameter	From	To	SEAL Material	From	To	Sacks or Pounds

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
☐ Other _____
Backfill placed from _____ ft. to _____ ft. Material _____
Gravel placed from _____ ft. to _____ ft. Size of gravel _____

(6) CASING/LINER

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:					☐	☐	☐	☐
					☐	☐	☐	☐

Drive Shoe used ☐ Inside ☐ Outside ☐ None
Final location of shoe(s) _____

(7) PERFORATIONS/SCREENS
☐ Perforations Method _____
☐ Screens Type _____ Material _____

From	To	Slot Size	Number	Diameter	Tele/pipe size	Casing	Liner
						☐	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour
☐ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time

Temperature of water _____ Depth Artesian Flow Found _____
Was a water analysis done? ☐ Yes By whom _____
Did any strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other _____
Depth of strata: _____

(9) LOCATION OF WELL (legal description)
County Deschutes
Tax Lot 10100 Lot _____
Township 18 N or (S) Range 11 (E) or W WM
Section 25 NW 1/4 SE 1/4
Lat ___°___'___" or _____ (degrees or decimal)
Long ___°___'___" or _____ (degrees or decimal)
Street Address of Well (or nearest address) _____
60095 Itopi Rd.

(10) STATIC WATER LEVEL
_____ ft. below land surface. Date _____
_____ ft. below land surface. Date _____
Artesian pressure _____ lb. per square inch Date _____

(11) WATER BEARING ZONES
Depth at which water was first found _____

From	To	Estimated Flow Rate	SWL

(12) WELL LOG Ground Elevation _____

Material	From	To	SWL
Well Backfilled 3/8 gravel	415	389	
filled from Bottom			
to Land (3' below) with			
4 yards sand grout			
5 sack mix.	389	-3	

Date Started 11/08/06 Completed 11/08/06

(unbonded) Water Well Constructor Certification
I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

WWC Number 1371 Date 11/08/06
Signed Gale R Brockett

(bonded) Water Well Constructor Certification
I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

WWC Number 1371 Date 11/08/06
Signed Gale R Brockett