

1- District
1- Supervisor (E)
1- R. O. (E)
1- R. O. (OAS)

DESC
9657

Contractor: Furnish 4 legible copies to COR
within 15 days after completion
of well

**U. S. FOREST SERVICE
REGION 6**

BID NO. R6-74-58

DESCHUTES NATIONAL National Forest
DIOSMIR LAKE CAMPGROUND
(Ranger Station, Work Center, Campground, etc.)
1/4 1/4 Section 5 T. 19 S. R. 8 E. W.M.

8 "Diam. from 0 ft. to 30 ft. Wall thickness 250.
"Diam. from ft. to ft. Wall thickness
"Diam. from ft. to ft. Wall thickness

Perforated ? ☐ Yes ☒ No

[illegible]

Screen installed? ☐ Yes ☒ No.

Manufacturer _____
Type _____
Diam _____ " Slot size _____ " Set from _____ ft. to _____ ft.
Diam _____ " Slot size _____ " Set from _____ ft. to _____ ft.

Static level 0 ft. below land surface. Date _____
Artesian pressure _____ lbs. per square inch. Date _____

Pump test made? ☐ Yes ☒ No If yes, Date _____
Yield: _____ gpm with _____ ft. drawdown after _____ hrs.
Yield: _____ gpm with _____ ft. drawdown after _____ hrs.
Yield: _____ gpm with _____ ft. drawdown after _____ hrs.
Bailer test _____ gpm with _____ ft. d.d. after _____ hrs.
Artesian flow _____ gpm Date _____
Temperature of water, _____ ° F. Date _____
NOTE: Drawdown is amount water level is lowered
below static level

Pump installed? ☐ Yes ☒ No

Name and type _____ hp. _____
Depth of intake _____ ft. below land surface. _____
Airline installed? ☐ Yes. ☐ No Length. _____ ft.

Diam. of well 8 inches. Depth drilled 150 ft.
Depth of completed well 150 ft.

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each formation change.

[illegible]

Work started 8-2-74
Completed _____ Abandoned 8-12-74

NAME Macy & Son Well Drilling
(person, firm, or corporation)
Address P.O. Box 1167 Bense, La.
Driller R.M. KIRKGE Date 8-24-74
(Signature)

R6-7400-5 (2/69)