RECEIVED
SEP 30 1958
STATE ENGINEER
SALEM, OREGON

OBSERVATION WELL DOUG 2043

WATER WELL REPORT
STATE OF OREGON

File Original and First Copy with the STATE ENGINEER, SALEM, OREGON

State Well No. 21/4W-19R(1)

State Permit No.

(1) OWNER:
Name S. E. Elwood (Pass Crk. Park - Douglas Co.)
Address Curtin Truck Service Company
Curtin, Oregon

(2) LOCATION OF WELL:
County Douglas Owner's number, if any—
S½ x SE ¼ Section 19 T. 21S R. 4 W.M.
Bearing and distance from section or subdivision corner
East side of Railroad - North of Pass Creek

(3) TYPE OF WORK (check):
New Well ☒ Deepening ☐ Reconditioning ☐ Abandon ☐
If abandonment, describe material and procedure in Item 11.

(4) PROPOSED USE (check):
Domestic ☒ Industrial ☐ Municipal ☐
Irrigation ☐ Test Well ☐ Other ☐

(5) TYPE OF WELL:
Rotary ☐ Driven ☐
Cable ☒ Jetted ☐
Dug ☐ Bored ☐

(6) CASING INSTALLED: Threaded ☐ Welded ☒
8" Diam. from 0 ft. to 16 ft. Gage Heavy
" Diam. from ft. to ft. Gage
" Diam. from ft. to ft. Gage

(7) PERFORATIONS: Perforated? ☐ Yes ☒ No
Type of perforator used
SIZE of perforations in. by in.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

(8) SCREENS: Well screen installed ☐ Yes ☐ No
Manufacturer's Name
Type Model No.
Diam. Slot size Set from ft. to ft.
Diam. Slot size Set from ft. to ft.

(9) CONSTRUCTION:
Was well gravel packed? ☐ Yes ☒ No Size of gravel:
Gravel placed from ft. to ft.
Was a surface seal provided? ☐ Yes ☐ No To what depth? ft.
Material used in seal—
Did any strata contain unusable water? ☐ Yes ☐ No
Type of water? Depth of strata
Method of sealing strata off

(10) WATER LEVELS:
Static level 15 ft. below land surface Date 8/16/58
Artesian pressure lbs. per square inch Date

Log Accepted by:
[Signed] S. E. Elwood (Owner) Date Sept 27, 1958

(11) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? ☐ Yes ☒ No If yes, by whom?
Yield: gal./min. with ft. drawdown after hrs.
" " " "
" " " "
Bailer test 34 gal./min. with 60 ft. drawdown after 2 hrs.
Artesian flow g.p.m. Date
Temperature of water Was a chemical analysis made? ☐ Yes ☐ No

(12) WELL LOG: Diameter of well 8 inches.
Depth drilled 110 ft. Depth of completed well 110 ft.
Formation: *Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.*

MATERIAL	FROM	TO
Yellow Clay	0	15
Gray Rock	15	110

Work started Aug. 12, 1958 Completed Aug. 16, 1958

(13) PUMP:
Manufacturer's Name
Type: H.P.

Well Driller's Statement:
This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME CARTER'S DRILLING & PUMP SERVICE
(Person, firm, or corporation) (Type or print)
Address 325 So. 2nd St., Springfield, Oregon
Driller's well number
[Signed] (Well Driller)
License No. 126 Date Aug. 21, 1958

(USE ADDITIONAL SHEETS IF NECESSARY)