

RECEIVED

JUL 19 1999

STATE OF OREGON WATER SUPPLY WELL REPORT (as required by ORS 537.765)

WATER RESOURCES DEPT SALEM, OREGON

WELL I.D. # L 29410 START CARD # 101271

Instructions for completing this report are on the last page of this form.

(1) OWNER: Well Number Name Downey Enterprises Address 974 N.W. Mahogany Ln. City Silver Dale State Wa. Zip 99383

(2) TYPE OF WORK: [X] New Well [X] Deepening [] Alteration (repair/recondition) [] Abandonment

(3) DRILL METHOD: [X] Rotary Air [] Rotary Mud [] Cable [] Auger [] Other

(4) PROPOSED USE: [X] Domestic [] Community [] Industrial [] Irrigation [] Thermal [] Injection [] Livestock [] Other

(5) BORE HOLE CONSTRUCTION: Special Construction approval [] Yes [X] No Depth of Completed Well 139 ft. Explosives used [] Yes [X] No Type Amount

Table with columns: HOLE Diameter, From, To, Material, SEAL From, To, Sacks or pounds. Contains handwritten 'N/A' entries.

How was seal placed: Method [] A [] B [] C [] D [] E [] Other

Backfill placed from ft. to ft. Material Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER: Table with columns: Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded. Includes rows for Casing and Liner.

Final location of shoe(s)

(7) PERFORATIONS/SCREENS: Table with columns: From, To, Slot size, Number, Diameter, Material, Type, Casing, Liner.

(8) WELL TESTS: Minimum testing time is 1 hour. Includes checkboxes for Pump, Bailer, Air, Flowing Artesian and a data table with handwritten 'N/A'.

Temperature of water Depth Artesian Flow Found Was a water analysis done? [] Yes By whom Did any strata contain water not suitable for intended use? [] Too little [] Salty [] Muddy [] Odor [] Colored [] Other Depth of strata:

(9) LOCATION OF WELL by legal description: County Douglas Latitude 43°19.330' Longitude 123°02.575' Township 26S N or S Range 3W E or W. WM. Section 10 1/4 1/4 Tax Lot 200 Lot Block Subdivision Street Address of Well (or nearest address) 22284 North Umana Hwy, Edley Park, OR 97447

(10) STATIC WATER LEVEL: ft. below land surface. N/A Date Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES: Depth at which water was first found

Table with columns: From, To, Estimated Flow Rate, SWL. Contains handwritten 'N/A' entries.

(12) WELL LOG: Ground Elevation

Table with columns: Material, From, To, SWL. Contains handwritten notes: 'The 4" liner was pulled from this well and it caused in the well will need a 5" steel liner put in to be useable. The owner decided to drill a new well at this time and put a steel liner in this well at a later date.'

Date started 7-14-99 Completed 7-14-99 (unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief. WWC Number Signed Date

(bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief. WWC Number 629 Signed Bruce A. Moore Date 7-15-99