

STATE OF OREGON
GEOTECHNICAL HOLE REPORT
 (as required by OAR 690-240-0035)

9/23/2026

(1) LANDOWNER/PROJECT Hole Nbr B1PROJECT NAME/NBR: ROSEBURG OR 9 21 26First Name RISHARD Last Name BALDWIN

Company _____

Address 1313 QUAIL LANECity ROSEBURG State OR Zip 97471**(2) TYPE OF WORK** ☒ New ☐ Deepening ☒ Abandonment
☐ Alteration (repair/recondition)**(3) CONSTRUCTION**☐ Rotary Air ☐ Hand Auger ☒ Hollow stem auger☐ Rotary Mud ☐ Cable ☐ Push Probe☐ Other _____**(4) TYPE OF HOLE:**☒ Uncased Temporary ☐ Cased Temporary☐ Uncased Permanent ☐ Cased Permanent☐ Other ☐ Slope Stability

Other: _____

(5) USE OF HOLE

GEOTECHNICAL SOIL

(6) BORE HOLE CONSTRUCTION Special Standard ☐ (Attach copy)Depth of Completed Hole 22.50 ft.

BORE HOLE			SEAL				sacks/
Dia	From	To	Material	From	To	Amt	lbs
8	0	22.5					

Backfill placed from _____ ft. to _____ ft. Material _____
 Filter pack from _____ ft. to _____ ft. Material _____ Size _____**(7) CASING/SCREEN**

Casing	Screen	Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd
☐	☐		☐				☐	☐	☐	☐
☐	☐		☐				☐	☐	☐	☐
☐	☐		☐				☐	☐	☐	☐
☐	☐		☐				☐	☐	☐	☐

(8) WELL TESTS

Type of Test	Yield (gal/min)	Drawdown	Drill Stem/ Pump Depth	Duration (hr)

Temperature _____ °F Lab analysis ☐ Yes By _____

Supervising Geologist/Engineer _____

Water quality concerns? ☐ Yes (describe below) TDS amount _____

From	To	Description	Amount	Units

(9) LOCATION OF HOLE (legal description)County DOUGLAS Twp 26.00 S N/S Range 5.00 W E/W WMSec 18 SW 1/4 of the NW 1/4 Tax Lot 604

Tax Map Number _____ Lot _____

Lat _____ " or 43.30993600 DMS or DDLong _____ " or -123.34417800 DMS or DD☐ Street address of hole ☒ Nearest address7961 OLD HWY 99 N ROSEBURG OREGON 97470**(10) STATIC WATER LEVEL**

Date _____ SWL(psi) + SWL(ft)

Existing Well / Pre-Alteration			
Completed Well			

WATER BEARING ZONES

Flowing Artesian? ☐ Dry Hole? ☐

Depth water was first found _____

SWL Date	From	To	Est Flow	SWL(psi)	+ SWL(ft)

(11) SUBSURFACE LOGGround Elevation 502.67 FT

Material	From	To
silts clay	0	15
rock core	15	22.5

Date Started 9/21/2026 Completed 9/21/2026**(12) ABANDONMENT LOG:**

Material	From	To	Amt	sacks/
Bentonite Chips	0	22.5	11	S

Date Started 9/21/2026 Completed 9/21/2026**Professional Certification** (to be signed by an Oregon licensed water or monitoring well constructor, Oregon registered geologist or professional engineer).

I accept responsibility for the construction, deepening, alteration, or abandonment work performed during the construction dates reported above. All work performed during this time is in compliance with Oregon geotechnical hole construction standards. This report is true to the best of my knowledge and belief.

License/Registration Number 10704 Date 9/23/2026First Name JACOB Last Name STIGALLAffiliation WESTERN STATES SOIL

ORIGINAL - WATER RESOURCES DEPARTMENT

THIS REPORT MUST BE SUBMITTED TO THE WATER RESOURCES DEPARTMENT WITHIN 30 DAYS OF COMPLETION OF WORK

Form Version:

9/23/2026

Water Bearing Zones

[illegible]

Casing Screen	Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd

Type of Test	Yield (gal/min)	Drawdown	Drill Stem/ Pump Depth	Duration (hr)

From	To	Description	Amount	Units

Damon Bickford drilled this boring

[illegible]

GEOTECHNICAL HOLE REPORT - Map with location identified must be attached and shall include an approximate scale and north arrow

DOUG 60299

9/23/2026

Map of Hole

