X/O

STATE OF OREGON

(HARING

#3

JAN 23 1991

085/30E/34.ab

(as required by ORS 537.765) WATE	R RESOURCES DEPART CARD) #
(1) OWNER. Wall Number:	CALS LOCEGOON OF WELL by legal description:
Name Doug Stills Address P. O Box 247	County Marney atitude Longitude
City Culuar State ort. Zip 97734	Township 25 Nort Range 30 Er W. WM. Section 34 NW47 NE 1/4
(2) TYPE OF WORK:	
New Well Deepen Recondition Abandon	Tax Lot Lot Block Subdivision  Street Address of Well (or nearest address)
(3) DRILL METHOD	Springs Rd.
Rotary Air Rotary Mud Cable	(10) STATIC WATER LEVEL:
Other	28 ft. below land surface. Date // - 19-83
(4) PROPOSED USE:	Artēsian pressure lb. per square inch. Date
☐ Domestic ☐ Community ☐ Industrial 🔀 Irrigation	(11) WATER BEARING ZONES:
☐ Thermal ☐ Injection ☐ Other	Depth at which water was first found 6 1 47.
(5) BORE HOLE CONSTRUCTION:  Special Construction approval Yes No Depth of Completed Well // 6 ft	
Vas Vo	61 105 2003 28
Explosives used Type Amount	
HOLE SEAL Amount	
Diameter From To Material From To sacks or pounds 16 0 22 Cement 0 22 15 sector	
	(12) WELL LOG: Ground elevation 3/00 47
	Material From To SWL
	Overburden 03
How was seal placed: Method	SANDSTONE - ED. 3 55 28
Backfill placed fromft, toft. Material	CINDERS - COURSO - BLACK 55 103
Gravel placed fromft, toft. Size of gravel	JAUA 103 110
(6) CASING/LINER:	
Diameter From To Gauge Steel Plastic Welded Threaded	
Casing: 12" O GO 250 X	
Liner:	
Final location of shoe(s)	
(7) PERFORATIONS/SCREENS:	
Perforations Method	
Screens Type Material	.
Slot Tele/pipe	,
From To size Number Diameter size Casing Liner	
	Date started
	(unbonded) Water Well Constructor Certification:
(8) WELL TESTS: Minimum testing time is 1 hour	I certify that the work I performed on the construction, alteration, abandonment of this well is in compliance with Oregon well construction.
Pump Bailer Air Artesian	standards. Materials used and information reported above are true to my be
Yield gal/min Drawdown Drill stem at Time	knowledge and belief
2003 34 2hr.	Signed Date
· .	
	(bonded) Water Well Constructor Certification:  I accept responsibility for the construction, alteration, or abandonment
Temperature of water 26 Depth Artesian Flow Found  Was a water analysis done?	work performed on this well during the construction dates reported above.
Was a water analysis done?	work performed during this time is in compliance with Oregon we construction standards. This report is true to the best of my knowledge ar
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other	belief. WWC Number 548
Depth of strata:	Signed 3. Forden Condan Date 1.18. 91