HARN 52716

STATE OF OREGON

WELL INFORMATION REPORT

· · · · · · · · · · · · · · · · · · ·	
(1) LAND OWNER Name Burth & Josephine Schroeder Well Number	(9) LOCATION OF WELL (legal description)
· · · · · · · · · · · · · · · · · · ·	County Harney
Address	Tax Lot Lot
City Burns State Of Zip	Township 23 Nor(S)Range 31 E or W WM
(2) TYPE OF WORK	Section 3 NW 1/4 NW 1/4
☐ Deepening ☐ Alteration (repair/recondition) ☐ Abandonment ☐ Conversion	Lato' or (degrees or decimal)
	Long or (degrees or decimal)
(3) DRILL METHOD	Street Address of Well (or nearest address)
☐ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger ☐ Cable Mud	Street Address of Well (of ficulest address)
Other	
(4) PROPOSED USE	(10) STATIC WATER LEVEL
☐ Domestic ☐ Community ☐ Industrial ☑ Irrigation	ft. below land surface. Date
☐ Thermal ☐ Injection ☐ Livestock ☐ Other	ft. below land surface. Date
(5) BORE HOLE CONSTRUCTION Special Construction: Yes No	Artesian pressure lb. per square inch Date
Depth of Completed Well 200 ft.	(11) WATER BEARING ZONES
Explosives used:	Depth at which water was first found
BORE HOLE SEAL	From To Estimated Flow Rate SWL
Diameter From To Material From To Sacks or Pounds	From 10 Estimated Flow Rate SWE
(2" 0 200	
	<u> </u>
How was seal placed: Method	
Other	(12) WELL LOG Ground Elevation
Backfill placed from ft. to ft. Material	Basin-fill Sediments, based From To SWL
Gravel placed from ft. to ft. Size of gravel	Basin-fill Sediments, based o 200 8
	A WILL LOS HARN BO AND HARN 50733
(6) CASING/LINER	I AHNIN 130F33
Diameter From To Gauge Steel Plastic Welded Threaded Casing: O 0	
Liner:	
Liner:	
Liner:	
Drive Shoe used Inside Outside None Final location of shoe(s)	3
That location of shoc(s)	
(7) PERFORATIONS/SCREENS	
Perforations Method	Date StartedCompleted Completed Complet
Screens Type Material	Date Started Completed Completed
From To Slot Number Diameter Tele/pipe Casing Liner	1
Size size	SOURCE OF DATA / INFO:
	File folder for application G-2507.
	File tolder for application 6-2007.
(8) WELL TESTS: Minimum testing time is 1 hour	<u> </u>
Pump Bailer Air Flowing Artesian	
Yield gal/min Drawdown Drill stem at Time	
Temperature of water Depth Artesian Flow Found	COMPILED BY: Ben Scandella
Was a water analysis done? Yes By whom	CONTRICTOR .
Did any strata contain water not suitable for intended use?	11.00 (0.10)
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other	DATE: 4/25/2018
Depth of strata:	