



**8/19/2026**

START CARD #

1083152

ORIGINAL LOG #

### (2a) PRE-ALTERATION

[illegible]

## (5) BORE HOLE CONSTRUCTION

| BORE HOLE |      |    | SEAL       |      |    | sacks/<br>lbs |     |
|-----------|------|----|------------|------|----|---------------|-----|
| Dia       | From | To | Material   | From | To |               | Amt |
|           |      |    |            |      |    |               |     |
|           |      |    | Calculated |      |    |               |     |
|           |      |    |            |      |    |               |     |
|           |      |    | Calculated |      |    |               |     |
|           |      |    |            |      |    |               |     |
|           |      |    | Calculated |      |    |               |     |
|           |      |    |            |      |    |               |     |
|           |      |    | Calculated |      |    |               |     |

| FILTER PACK |    |          |      |
|-------------|----|----------|------|
| From        | To | Material | Size |
|             |    |          |      |
|             |    |          |      |
|             |    |          |      |

## (6) CASING/LINER

[illegible]

## (7) PERFORATIONS/SCREENS

[illegible]

**(8) WELL TESTS:** Minimum testing time is 1 hour

| Type of Test | Yield<br>(gal/min ) | Drawdown | Drill Stem/<br>Pump Depth | Duration<br>(hr) |
|--------------|---------------------|----------|---------------------------|------------------|
|              |                     |          |                           |                  |
|              |                     |          |                           |                  |
|              |                     |          |                           |                  |
|              |                     |          |                           |                  |
|              |                     |          |                           |                  |

## Water Quality Concerns

[illegible]

### **(10) STATIC WATER LEVEL**

[illegible]

## (11) WELL LOG

[illegible]

---



---

Name of person(s) who assisted with construction and Trainee License # / Helper #

| Assistant Name | Type | # |
|----------------|------|---|
|                |      |   |
|                |      |   |
|                |      |   |
|                |      |   |

### Comments/Remarks

wells or hole was 4" stove pipe. about 6' long with hole below. pulled pipe out. poured bentonite. total depth 18'