NC

NOTICE TO WATER WELL CONTRACTOR
The original and first copy of this report are to be filed with the STATE ENGINEER, SALEM, OREGON 97310 within 30 days from the date of well completion.

RECEIVED
OCT 12 1966
STATE ENGINEER
OREGON

WATER WELL REPORT
STATE OF OREGON
(Please type or print)

6445
HANN
G6901

State Well No. 23/32½-10 P cd

State Permit No.

(1) OWNER:
Lester & Hilda Tice
Name Mrs. Wesley Claunch
Address
Burns, Oregon

(2) LOCATION OF WELL:
County Harney Driller's well number
SE ¼ SW ¼ Section 10 T. 23 S R. 32½ E W.M.
Bearing and distance from section or subdivision corner
1400' E of W section line
500' N of S section line

(3) TYPE OF WORK (check):
New Well ☒ Deepening ☐ Reconditioning ☐ Abandon ☐
If abandonment, describe material and procedure in Item 12.

(4) PROPOSED USE (check):
Domestic ☐ Industrial ☐ Municipal ☐
Irrigation ☒ Test Well ☐ Other ☐

(5) TYPE OF WELL:
Rotary ☐ Driven ☐
Cable ☒ Jetted ☐
Dug ☐ Bored ☐

(6) CASING INSTALLED:
Threaded ☐ Welded ☒
12" Diam. from 0 ft. to 40 ft. Gage ¼"
" Diam. from ft. to ft. Gage
" Diam. from ft. to ft. Gage

(7) PERFORATIONS:
Perforated? ☐ Yes ☒ No
Type of perforator used
Size of perforations in. by in.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

(8) SCREENS:
Well screen installed? ☐ Yes ☒ No
Manufacturer's Name
Model No.
Diam. Slot size Set from ft. to ft.
Diam. Slot size Set from ft. to ft.

(9) CONSTRUCTION:
Well seal—Material used in seal puddled clay
Depth of seal 18 ft. Was a packer used? no
Diameter of well bore to bottom of seal 15 in.
Were any loose strata cemented off? ☐ Yes ☒ No Depth
Was a drive shoe used? ☒ Yes ☐ No
Was well gravel packed? ☐ Yes ☒ No Size of gravel:
Gravel placed from ft. to ft.
Did any strata contain unusable water? ☐ Yes ☒ No
Type of water? depth of strata
Method of sealing strata off

(10) WATER LEVELS:
Static level 6 ft. below land surface Date 9-12-66
Artesian pressure lbs. per square inch Date

(11) WELL TESTS:
Drawdown is amount water level is lowered below static level
Was a pump test made? ☒ Yes ☐ No If yes, by whom? driller
Yield: 1118 gal./min. with 33 ft. drawdown after 3 hrs.
" " " "
" " " "
Bailer test gal./min. with ft. drawdown after hrs.
Artesian flow g.p.m. Date
Temperature of water Was a chemical analysis made? ☐ Yes ☒ No

(12) WELL LOG:
Diameter of well below casing 12"
Depth drilled 205 ft. Depth of completed well 205 ft.
Formation: *Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.*

MATERIAL	FROM	TO
brown soil	0	19
blue clay	19	20
fine sand with water	20	22
blue clay--trickles of water	22	90
hard sandstone grey w/water	90	136
conglomerate of green clay, pumice, brown clay, hard black rock w/ water in sand-stone	136	205
(note) work started May 20 1966; quit and pulled off job May 27.		
Resumed work Sept. 10, 1966		
Finished job Sept. 15.		

Work started 19 Completed 19
Date well drilling machine moved off of well Sept. 16 1966

(13) PUMP:
Manufacturer's Name
Type: H.P.

Water Well Contractor's Certification:
This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME Skinner & Sons
(Person, firm or corporation) (Type or print)
Address Crane, Oregon

Drilling Machine Operator's License No. 10
[Signed] Mrs. Forrest Skinner
(Water Well Contractor)
Contractor's License No. 372 Date Sept. 16, 1966

(USE ADDITIONAL SHEETS IF NECESSARY)