

(1) OWNER:

Name W.B. Clayton

Address Burns, Oregon

(2) LOCATION OF WELL:

County Hernando

Owner's number, if any /

R. F. D. or Street No.

Bearing and distance from section or subdivision corner

(3) TYPE OF WORK (check):

Drill well ☐ Deepening ☐ Reconditioning ☒ Abandon ☐

On abandonment, describe material and procedure in Item 11.

(4) PROPOSED USE (check):

Domestic ☐ Industrial ☐ Municipal ☐

Irrigation ☒ Test Well ☐ Other ☐

(5) EQUIPMENT:

Rotary ☐

Cable ☒

Dug Well ☐

(6) CASING INSTALLED:

Threaded ☐ Welded ☐

FROM	ft. to	ft.	Diam.	Gage or Wall
"	"	"	"	"
"	"	"	"	"
"	"	"	"	"
"	"	"	"	"
"	"	"	"	"

If gravel packed

Diameter of Bore	from ft.	to ft.
"	"	"
"	"	"
"	"	"
"	"	"
"	"	"

Type and size of shoe or well ring

Size of gravel:

Describe joint

(7) PERFORATIONS:

Type of perforator used

SIZE of perforations	in., length, by	in.
FROM	ft. to	ft.
"	"	"
"	"	"
"	"	"
"	"	"
"	"	"

SCREENS:

Give Manufacturer's Name, Model No. and Size

(8) CONSTRUCTION:

Was a surface sanitary seal provided? ☐ Yes ☐ No To what depth ft.

Were any strata sealed against pollution? ☐ Yes ☐ No

If yes, note depth of strata

FROM ft. to ft.

METHOD OF SEALING

(9) WATER LEVELS:

Depth at which water was first found ft.

Standing level before perforating ft.

Standing level after perforating ft.

Log Accepted by:

[Signed] _____ Dated _____, 19____
Owner

(10) WELL TESTS:

Was a pump test made? ☐ Yes ☐ No If yes, by whom?

Yield:	gal./min. with	ft. draw down after	hrs.
"	"	"	"
"	"	"	"

Artesian flow _____ g.p.m.

Shut-in pressure _____ lbs. per square inch.

Boiler test _____ g.p.m. with _____ ft. drawdown

Temperature of water _____ Was a chemical analysis made? ☐ Yes ☐ No

Was electric log made of well? ☐ Yes ☐ No

(11) WELL LOG:

Diameter of well, _____ inches.

Total depth _____ ft. Depth of completed well _____ ft.

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

ft. to ft. repair on well No. ~~1~~ 1
" " Installed ~~20~~ 210ft. of
" " 16in. O.D, 1/4 in. wall
" " casing,

" " Bottom 145ft. perforated
" " with six rows of 1/4 in. by
" " 4in. torch perforations
" " per ft.

" " Installed 20ft. 5in. of
" " liner in bottom of 16in.
" " casing.

" " Pulled 80 ft. of 18in.
" " O.D. casing.

Ground elevation at well site 4150 feet above mean sea level.

Work started 8/24 1957 Completed 10/12 1957

Well Driller's Statement:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME John A. VanMeter (Typed or printed)

Address Box 204 Malin, Oregon

Driller's well number 170

[Signed] John A. VanMeter (Well Driller)

License No. 170 Dated Dec 15, 1957