#2

RECEIVED
DEC 14 1960
STATE ENGINEER
SALEM, OREGON

Jack
11584

File Original and First Copy with the STATE ENGINEER, SALEM, OREGON

WATER WELL REPORT
STATE OF OREGON

State Well No. 37/1W-6R1

State Permit No. G1894

(1) OWNER:

Name Cummins Diesel

Address 909 E McAndrews Road
Medford, Oregon

(2) LOCATION OF WELL:

County Jackson Owner's number, if any—

SE ¼ SE ¼ Section 6 T. 37S R. 1W W.M.

Bearing and distance from section or subdivision corner well is located 526'N & 4855'E from the SW Corner of Section 6

(3) TYPE OF WORK (check):

New Well ☒ Deepening ☐ Reconditioning ☐ Abandon ☐

If abandonment, describe material and procedure in Item 11.

(4) PROPOSED USE (check):

Domestic ☐ Industrial ☒ Municipal ☐
Irrigation ☐ Test Well ☐ Other ☐

(5) TYPE OF WELL:

Rotary ☐ Driven ☐
Cable ☒ Jetted ☐
Dug ☐ Bored ☐

(6) CASING INSTALLED: Threaded ☐ Welded ☒

6" Diam. from 0 ft. to 10½ ft. Gage 3/16

" Diam. from ft. to ft. Gage

" Diam. from ft. to ft. Gage

(7) PERFORATIONS: Perforated? ☐ Yes ☒ No

Type of perforator used

SIZE of perforations in. by in.

perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

(8) SCREENS: Well screen installed ☐ Yes ☒ No

Manufacturer's Name

Type Model No.

Diam. Slot size Set from ft. to ft.

Diam. Slot size Set from ft. to ft.

(9) CONSTRUCTION:

Was well gravel packed? ☐ Yes ☒ No Size of gravel:

Gravel placed from ft. to ft.

Was a surface seal provided? ☐ Yes ☒ No To what depth? ft.

Material used in seal—

Did any strata contain unusable water? ☐ Yes ☒ No

Type of water? Depth of strata

Method of sealing strata off DRIVE SHOE

(10) WATER LEVELS:

Static level 30 ft. below land surface Date

Artesian pressure lbs. per square inch Date

Log Accepted by:

[Signed] Don Jones (Owner) Date 12/12, 1960

(11) WELL TESTS: Drawdown is amount water level is lowered below static level

Was a pump test made? ☐ Yes ☒ No If yes, by whom?

Yield: gal./min. with ft. drawdown after hrs.

" " " "

" " " "

Bailer test 30 gal./min. with 100 ft. drawdown after hrs.

Artesian flow g.p.m. Date

Temperature of water Was a chemical analysis made? ☐ Yes ☒ No

(12) WELL LOG: Diameter of well 6 inches.

Depth drilled 242 ft. Depth of completed well 242 ft.

Formation: *Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.*

MATERIAL	FROM	TO
SOIL	0	1
HARDPAN & BOULDERS	1	6
DARK GREY SHALE	6	22
HARD STREEK OF SAND-STONE	22	24
BROWN SHALE	24	50
BLUE-GREEN SANDSTONE	50	130
GREY SAND STONE	130	155
DARK BLUE SLATE	155	175
GREY SANDSTONE	175	241
SOLID ROCK	241	242
1ST WATER AT 40'	1 GAL PER M.	

Work started 19 . Completed 19

(13) PUMP:

Manufacturer's Name 2" Submersible Pump

Type: H.P. 7.5

Well Driller's Statement:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME Crater Well Drilling (Person, firm, or corporation) (Type or print)

Address 3061 Crater Lake Ave. Medford Oregon

Driller's well number

[Signed] (Well Driller)

License No. 83 Date 19

(USE ADDITIONAL SHEETS IF NECESSARY)