

NOTICE TO WATER WELL CONTRACTOR

The original and first copy of this report are to be filed with the

STATE ENGINEER, SALEM, OREGON 97310 within 30 days from the date of well completion.

RECEIVED

OCT 27 1965

WATER WELL REPORT

STATE ENGINEER

STATE OF OREGON

(Please type or print)

State Well No.

37/2w-17

State Permit No.

(1) OWNER:

Name Don Patterson
Address 841 Pine St.
Central Point, Cal.

(2) LOCATION OF WELL:

County Jackson Driller's well number 338
1/4 Section 17 T. 7 S. R. 2 W. M.
Bearing and distance from section or subdivision corner

(3) TYPE OF WORK (check):

New Well ☒ Deepening ☐ Reconditioning ☐ Abandon ☐
Abandonment, describe material and procedure in Item 12.

(4) PROPOSED USE (check):

Domestic ☒ Industrial ☐ Municipal ☐
Irrigation ☐ Test Well ☐ Other ☐

(5) TYPE OF WELL:

Rotary ☐ Driven ☐
Cable ☒ Jetted ☐
Dug ☐ Bored ☐

(6) CASING INSTALLED:

Threaded ☐ Welded ☐

6" Diam. from 0 ft. to 19 1/2 ft. Gage 350
" Diam. from ft. to ft. Gage
" Diam. from ft. to ft. Gage

(7) PERFORATIONS:

Perforated? ☐ Yes ☒ No

Type of perforator used

Size of perforations in. by in.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

(8) SCREENS:

Well screen installed? ☐ Yes ☒ No

Manufacturer's Name
Model No.
Slot size Set from ft. to ft.
Diam. Slot size Set from ft. to ft.

(9) CONSTRUCTION:

Well seal—Material used in seal Extruded Cement based
Depth of seal 19 ft. Was a packer used? no
Diameter of well bore to bottom of seal 10 in.
Were any loose strata cemented off? ☐ Yes ☒ No Depth
Was a drive shoe used? ☐ Yes ☒ No
Was well gravel packed? ☐ Yes ☒ No Size of gravel:
Gravel placed from ft. to ft.
Did any strata contain unusable water? ☐ Yes ☒ No
Type of water depth of strata
Method of sealing strata off

(10) WATER LEVELS:

Static level 13 ft. below land surface Date 10-4-65
Artesian pressure lbs. per square inch Date

(11) WELL TESTS:

Drawdown is amount water level is lowered below static level

Was a pump test made? ☐ Yes ☒ No If yes, by whom?

Yield: gal./min. with ft. drawdown after hrs.
" " " "
" " " "
Bailer test 1.9 gal./min. with 140 ft. drawdown after 1 hrs.
Artesian flow g.p.m. Date
Temperature of water 56 Was a chemical analysis made? ☐ Yes ☒ No

(12) WELL LOG:

Diameter of well below casing 6

Depth drilled 172 ft. Depth of completed well 172 ft.

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

MATERIAL	FROM	TO
<u>Dr. Granite</u>	<u>0</u>	<u>2</u>
<u>Soft Granite</u>	<u>2</u>	<u>8</u>
<u>" " "</u>	<u>8</u>	<u>24</u>
<u>" Greenish Grey</u>	<u>24</u>	<u>68</u>
<u>Hard Granite</u>	<u>68</u>	<u>172</u>

Work started 9-20 1965 Completed 10-4 1965
Date well drilling machine moved off of well 10-4 1965

(13) PUMP:

Manufacturer's Name
Type: H.P.

Water Well Contractor's Certification:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME M.D. SHULTS Well Drilling
(Person, firm or corporation) (Type or print)

Address 2034 W. main Medford

Drilling Machine Operator's License No. 94

[Signed] M.D. Shults
(Water Well Contractor)

Contractor's License No. 105 Date 10-4 1965