JACK 13826

NOTICE TO WATER WELL CONTRACTOR
The original and first copy of this report are to be filed with the STATE ENGINEER, SALEM, OREGON 97310 within 30 days from the date of well completion.

RECEIVED APR 17 1969 STATE ENGINEER SALEM OREGON

WATER WELL REPORT
STATE OF OREGON
(Please type or print)

RECEIVED MAY 2 1969 STATE ENGINEER SALEM OREGON

State Well No. 37/2W-34

State Permit No.

(1) OWNER:
Name W. S. Ferris
Address 3859 Bellinger Lane
Medford, Oregon 97501

(2) LOCATION OF WELL:
County Jackson Driller's well number #1
¼ ¼ Section 34 T. 37 R. 2W W.M.
Bearing and distance from section or subdivision corner

(3) TYPE OF WORK (check):
New Well XX Deepening ☐ Reconditioning ☐ Abandon ☐
If abandonment, describe material and procedure in Item 12.

(4) PROPOSED USE (check):
Domestic XX Industrial ☐ Municipal ☐
Irrigation ☐ Test Well ☐ Other ☐

(5) TYPE OF WELL:
Rotary XX Driven ☐
Cable ☐ Jetted ☐
Dug ☐ Bored ☐

(6) CASING INSTALLED:
Threaded ☐ Welded XX
6" Diam. from 0 ft. to 73 ft. Gage .250
" Diam. from ft. to ft. Gage
" Diam. from ft. to ft. Gage

(7) PERFORATIONS:
Perforated? XX Yes ☐ No
Type of perforator used What type perf? torch
Size of perforations ¼ in. by 1 1/8 in.
30 perforations from 33 ft. to 73 ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

(8) SCREENS:
Well screen installed? ☐ Yes ☒ No
Manufacturer's Name
Type Model No.
Diam. Slot size Set from ft. to ft.
Diam. Slot size Set from ft. to ft.

(9) CONSTRUCTION:
Well seal—Material used in seal bentonite
Depth of seal 20 ft. Was a packer used?
Diameter of well bore to bottom of seal 9 in.
Were any loose strata cemented off? ☐ Yes XX No Depth
Was a drive shoe used? XX Yes ☐ No
Was well gravel packed? ☐ Yes ☐ No Size of gravel:
Gravel placed from ft. to ft.
Did any strata contain unusable water? ☐ Yes XX No
Type of water? depth of strata
Method of sealing strata off

(10) WATER LEVELS:
Static level 10 ft. below land surface Date 2.24.69
Artesian pressure lbs. per square inch Date

(11) WELL TESTS:
Drawdown is amount water level is lowered below static level
Was a pump test made? ☒ Yes ☐ No If yes, by whom? ~~driller~~ Stokiyin Pump
Yield: 10 gal./min. with 73 ft. drawdown after 12 hrs.
" " " "
" " " "
Bailer test gal./min. with ft. drawdown after hrs.
Artesian flow g.p.m. Date
Temperature of water 58 Was a chemical analysis made? ☐ Yes ☒ No

(12) WELL LOG:
Diameter of well below casing 6"
Depth drilled 83 ft. Depth of completed well 83 ft.
Formation: *Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.*

MATERIAL	FROM	TO
~~top soil & clay~~	~~0~~	~~10~~
clay, gravel, med. boulders	10	40
clay, sand, gravel	40	73
grey hard rock	73	83

Work started 2/20/69 19 Completed 2/24/69 19
Date well drilling machine moved off of well 2/24/69 19

(13) PUMP:
Manufacturer's Name
Type: H.P.

Water Well Contractor's Certification:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME Rotary Drilling Co.
(Person, firm or corporation) (Type or print)
Address 1044 W. 12th, Medford, Oregon
Drilling Machine Operator's License No. 635
[Signed] [signature]
(Water Well Contractor)
Contractor's License No. 338 Date 3/12/69, 19

(USE ADDITIONAL SHEETS IF NECESSARY)