

RECEIVED

JUN 7 1960

STATE ENGINEER

WATER WELL REPORT

STATE OF OREGON

State Well No. 39/2W-3

State Permit No. _____

File Original and
First Copy with the
STATE ENGINEER,
SALEM, OREGON

(1) OWNER:

Name Arnold Bohner
Address Rt-1 Box 60
Central Point Oregon

(2) LOCATION OF WELL:

County Jackson Owner's number, if any—
1/4 1/4 Section 3 T. 37 R. 2W W.M.
Bearing and distance from section or subdivision corner
200' from 180' E of section 3.
60' N of Property line

(3) TYPE OF WORK (check):

New Well ☒ Deepening ☐ Reconditioning ☐ Abandon ☐
If abandonment, describe material and procedure in Item 11.

PROPOSED USE (check):

Domestic ☐ Industrial ☐ Municipal ☐
Irrigation ☐ Test Well ☐ Other ☒

(5) TYPE OF WELL:

Rotary ☐ Driven ☐
Cable ☐ Jetted ☐
Dug ☐ Bored ☒

(6) CASING INSTALLED:

Threaded ☐ Welded ☐

18" Diam. from 0 ft. to 3.0 ft. Gage Concrete
" Diam. from _____ ft. to _____ ft. Gage _____
" Diam. from _____ ft. to _____ ft. Gage _____

(7) PERFORATIONS:

Perforated? ☒ Yes ☐ No

Type of perforator used _____

SIZE of perforations 1 in. by 1 in.
108 perforations from 3 ft. to 3.0 ft.
perforations from _____ ft. to _____ ft.
perforations from _____ ft. to _____ ft.
perforations from _____ ft. to _____ ft.
perforations from _____ ft. to _____ ft.

(8) SCREENS:

Well screen installed ☐ Yes ☒ No

Manufacturer's Name _____
Type _____ Model No. _____
n. Slot size _____ Set from _____ ft. to _____ ft.
Slot size _____ Set from _____ ft. to _____ ft.

(9) CONSTRUCTION:

Was well gravel packed? ☐ Yes ☒ No Size of gravel. _____
Gravel placed from _____ ft. to _____ ft.
Was a surface seal provided? ☒ Yes ☐ No To what depth? 3 ft.
Material used in seal— Concrete
Did any strata contain unusable water? ☐ Yes ☒ No
Type of water? _____ Depth of strata _____
Method of sealing strata off _____

(10) WATER LEVELS:

Static level 6 ft. below land surface Date 4-30-60
Artesian pressure _____ lbs. per square inch Date _____

Log Accepted by: _____

[Signed] Arnold Bohner Date April 30, 1960
(Owner)

(11) WELL TESTS:

Drawdown is amount water level is lowered below static level

Was a pump test made? ☒ Yes ☐ No If yes, by whom?

Yield: 15 gal./min. with 2.0 ft. drawdown after 3 hrs.
" " " " " "
" " " " " "

Bailer test gal./min. with _____ ft. drawdown after _____ hrs.

Artesian flow g.p.m. Date _____

Temperature of water— _____ Was a chemical analysis made? ☐ Yes ☒ No

(12) WELL LOG:

Diameter of well 18 inches.

Depth drilled 31 ft. Depth of completed well 30 ft.

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

MATERIAL	FROM	TO
TOP SOIL	0	4'
Silt + Sand	4'	6'
Sand water	6'	8'
Clay	8'	15'
Gravel + water	15'	18'
Clay	18'	28'
Hard yellow clay	28'	31'

Work started 4-30 1960 Completed 4-30 1960

(13) PUMP:

Manufacturer's Name _____
Type _____ H.P. _____

Well Driller's Statement:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME Shand Bros Drilling
(Person, firm, or corporation) (Type or print)

Address 412 N 3rd Central Point

Driller's well number _____

[Signed] Wayne W. Shand
(Well Driller)

License No. 44 Date 4-30, 1960