

Sack
20840 WATER WELL REPORT
STATE OF OREGON

State Well No. 39/2-30K
State Permit No.

(1) OWNER:

Name W.L. Leonard
Address 850 Neil Creek Road
Ashland, Oregon

(2) LOCATION OF WELL:

County JACKSON Owner's number, if any—
N.W. 1/4 S.E. 1/4 Section 30 T. 39S R. 2E W.M.
Bearing and distance from section or subdivision corner
1284' W. of N.E. corner of SE 1/4
of Sect. 30 thence 100' S
to well

(3) TYPE OF WORK (check):

New Well ☐ Deepening ☒ Reconditioning ☐ Abandon ☐
If abandonment, describe material and procedure in Item 11.

PROPOSED USE (check):

Domestic ☒ Industrial ☐ Municipal ☐
Irrigation ☐ Test Well ☐ Other ☐

(5) TYPE OF WELL:

Rotary ☐ Driven ☐
Cable ☒ Jetted ☐
Dug ☐ Bored ☐

(6) CASING INSTALLED:

Threaded ☐ Welded ☒
5" Diam. from 0 ft. to 7 ft. Gage 1.6
5" Diam. from 7 ft. to 15 ft. Gage 1.6
5" Diam. from 15 ft. to 35 ft. Gage 1.6

(7) PERFORATIONS:

Perforated? ☐ Yes ☐ No
Type of perforator used
SIZE of perforations in. by in.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

(8) SCREENS:

Well screen installed ☐ Yes ☐ No
Manufacturer's Name
Type Model No.
Diam. Slot size Set from ft. to ft.
Diam. Slot size Set from ft. to ft.

(9) CONSTRUCTION:

Was well gravel packed? ☐ Yes ☐ No Size of gravel:
Gravel placed from ft. to ft.
Was a surface seal provided? ☒ Yes ☐ No To what depth? 3.5 ft.
Material used in seal— cement
Did any strata contain unusable water? ☒ Yes ☐ No
Type of water? Hard Iron Depth of strata 0' to 30'
Method of sealing strata off cement

(10) WATER LEVELS:

Static level 12 ft. below land surface Date Oct 26-58
Artesian pressure lbs. per square inch Date

Log Accepted by:

[Signed] W.L. Leonard Date Oct. 30, 1958
(Owner)

(11) WELL TESTS:

Drawdown is amount water level is lowered below static level
Was a pump test made? ☐ Yes ☒ No If yes, by whom?
Yield: gal./min. with ft. drawdown after hrs.
" " " "
" " " "
Bailer test 4 gal./min. with 140' ft. drawdown after 10 hrs.
Artesian flow g.p.m. Date
Temperature of water 50° Was a chemical analysis made? ☐ Yes ☒ No

(12) WELL LOG:

Diameter of well 6 inches.
Depth drilled 78 ft. Depth of completed well 171 ft.

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

MATERIAL	FROM	TO
Grey Shale	93	171
picked up water in this shale at 140' and at 154'		
the old casing was broken in the welded joints at 12' + 38". The surface water was unfit for use very brown, brackish color & had a bad odor. Cased this out with a 5" lagage steel pipe inside the old 6" casing & poured the space between full of cement		
RECEIVED		
NOV 5 1958		
STATE ENGINEER		
SALEM, OREGON		

Work started 10-8 1958 Completed 10-25 1958

(13) PUMP:

Manufacturer's Name Advance
Type: Jet H.P. 1

Well Driller's Statement:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME DALLAS S DELAP
(Person, firm, or corporation) (Type or print)

Address 749 Eagle Mill Rd Ashland

Driller's well number 41

[Signed] Dallas S Delap
(Well Driller)

License No. 36 Date 10-25, 1958