

14

JACK 31018

JACK 31018 AUG 28 1991

38S/1W/9

STATE OF OREGON WATER WELL REPORT (as required by ORS 537.765)

WATER RESOURCES DEPT. SALEM, OREGON (START CARD) # 24419

(1) OWNER: Name John Gutierrez Well Number: 4 Address P.O. Box 1217 City Eagle Point, State OR Zip 97524

(2) TYPE OF WORK: [X] New Well [] Deepen [] Recondition [] Abandon

(3) DRILL METHOD [X] Rotary Air [] Rotary Mud [] Cable [] Other

(4) PROPOSED USE: [X] Domestic [] Community [] Industrial [] Irrigation [] Thermal [] Injection [] Other

(5) BORE HOLE CONSTRUCTION: Special Construction approval Yes No Depth of Completed Well 110 ft. Explosives used [] [X] Type Amount

Table with columns: HOLE Diameter, SEAL Material, Amount sacks or pounds. Row 1: 10" 0 to 19, Cement, 0 to 19, 9 Sacks. Row 2: 6" 19 to 110, Cement, 0 to 19, 9 Sacks.

How was seal placed: Method [] A [] B [X] C [] D [] E [X] Other 14' 10" Conductor Pipe Backfill placed from ft. to ft. Material Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER: Table with columns: Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded. Casing: 6" +1 19 250 [X] [] [X] []. Liner: 4" 0 110 160 [] [X] [X] []. Final location of shoe(s) 19 1/2

(7) PERFORATIONS/SCREENS: [X] Perforations Method Skil saw [] Screens Type Material. Table with columns: From, To, Slot size, Number, Diameter, Tele/pipe size, Casing, Liner. Row 1: 50, 110, 1/8x6, 147, [] [X]

(8) WELL TESTS: Minimum testing time is 1 hour [] Pump [] Bailer [X] Air [] Flowing Artesian Yield gal/min 30+ Drawdown Drill stem at 110 Time 1 hr. Temperature of water 57 Depth Artesian Flow Found Was a water analysis done? [] Yes By whom Did any strata contain water not suitable for intended use? [] Too little [] Salty [] Muddy [] Odor [] Colored [] Other Depth of strata

(9) LOCATION OF WELL by legal description: County Jackson Latitude Longitude Township 38S N or S. Range 1W E or W, WM. Section 9 Tax Lot 201 Lot Block Subdivision Street Address of Well (or nearest address) End of Northridge Terrace, Phoenix

(10) STATIC WATER LEVEL: 7 ft. below land surface. Date 6-20-91 Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES: Depth at which water was first found 39. Table with columns: From, To, Estimated Flow Rate, SWL. Row 1: 39, 46, 30+, 7

(12) WELL LOG: Ground elevation. Table with columns: Material, From, To, SWL. Row 1: Clay, 0, 8. Row 2: Sand & Gravel, 8, 14. Row 3: Gray Claystone, 14, 39. Row 4: Sandstone - Broken, 39, 46, 7. Row 5: Gray Claystone, 46, 110

Date started 6-20-91 Completed 6-20-91

(unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief. WWC Number Signed Date

(bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. all work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief. WWC Number 1478 Signed Date 8-9-91