

14

STATE OF OREGON
WATER WELL REPORT
(as required by ORS 537.765)

Jack
31043

RECEIVED

385/26/8

SEP - 6 1991 (START CARD) # 31032

(1) OWNER: Name Don Beck Well Number: WATE
Address 2551a Scenic Ave
City Central Point State Ore Zip 97502

(2) TYPE OF WORK:
☒ New Well ☐ Deepen ☐ Recondition ☐ Abandon

(3) DRILL METHOD
☒ Rotary Air ☐ Rotary Mud ☐ Cable
☐ Other

(4) PROPOSED USE:
☒ Domestic ☐ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval Yes ☐ No ☒ Depth of Completed Well 410'
Explosives used ☐ Type _____ Amount _____

HOLE		SEAL		Amount	
Diameter	From To	Material	From To	sacks	pounds
<u>6"</u>	<u>41'</u> <u>19'</u>	<u>Benmore</u>	<u>0</u> <u>19'</u>	<u>12</u>	

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
☒ Other Poured in dry
Backfill placed from _____ ft. to _____ ft. Material _____
Gravel placed from _____ ft. to _____ ft. Size of gravel _____

Diameter		From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:		<u>6"</u>	<u>41'</u> <u>19'</u>	<u>200</u>	☒	☐	☒	☐
Liner:		<u>n/a</u>			☐	☐	☐	☐

Final location of shoe(s) _____

(7) PERFORATIONS/SCREENS:
☐ Perforations Method _____
☐ Screens Type _____ Material _____

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
		<u>n/a</u>				☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour
☐ Pump ☐ Bailer ☒ Air ☐ Flowing ☐ Artesian
Yield gal/min 3 1/2 Drawdown 410' Drill stem at 410' Time 1 hr.

Temperature of water 53° Depth Artesian Flow Found _____
Was a water analysis done? ☐ Yes By whom _____
Did any strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other _____
Depth of strata: _____

(9) LOCATION OF WELL by legal description:
County OSN Latitude _____ Longitude _____
Township 38 North Range 2 E or W WM.
Section 8 1/4 1/4
Tax Lot 100 Lot _____ Block _____ Subdivision _____
Street Address of Well (or nearest address) 5591 W. Gellish Ck. near Mosher Cr.

(10) STATIC WATER LEVEL:
68' ft. below land surface. Date 8/11/91
Artesian pressure _____ lb. per square inch. Date _____

(11) WATER BEARING ZONES:

Depth at which water was first found 394'

From	To	Estimated Flow Rate	SWL
<u>394</u>	<u>395</u>	<u>32</u>	<u>68</u>

(12) WELL LOG: Ground elevation _____

Material	From	To	SWL
<u>CLAYSTONE</u>	<u>Brown</u>	<u>0</u>	<u>3</u>
<u>SANDSTONE</u>	<u>Brown</u>	<u>3</u>	<u>12</u>
<u>SANDSTONE</u>	<u>Blue</u>	<u>12</u>	<u>46</u>
<u>BASALT</u>	<u>Blue</u>	<u>46</u>	<u>394</u>
<u>BASALT</u>	<u>Blue</u>	<u>394</u>	<u>395</u> <u>68</u>
<u>BASALT</u>	<u>Blue</u>	<u>395</u>	<u>410</u>

Date started 8/10/91 Completed 8/11/91

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.
Signed _____ WWC Number _____
Date _____

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.
Signed _____ WWC Number 1457
Date 8/15/91