JACK 32191 RECEIVED 38S/1W/9c

STATE OF OREGON
WATER WELL REPORT
(as required by ORS 537.765)

JACK 32191
STUDEBAKER DRILLING, INC.
1133 S. Riverside #16
Medford, Oregon 97501

DEC 21 1992
WATER RESOURCES DEPT. OREGON

(START CARD) # 44991

(1) OWNER: Well Number _____
Name William Madden
Address 1902 Houston Road
City Phoenix State Ore Zip 97535

(2) TYPE OF WORK:
☐ New Well ☒ Deepen ☒ Recondition ☐ Abandon

(3) DRILL METHOD:
☒ Rotary Air ☐ Rotary Mud ☐ Cable
☐ Other _____

(4) PROPOSED USE:
☒ Domestic ☐ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

(5) BORE HOLE CONSTRUCTION:
Special Construction approval ☐ Yes ☒ No Depth of Completed Well 300 ft.
Explosives used ☐ Yes ☒ No Type _____ Amount _____

HOLE Diameter	From	To	SEAL Material	From	To	Amount sacks or pounds
10	0	58	bentonite	0	25	12sacks
			chip	25	30	3 sacks
6	58	300				

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
☒ Other poured
Backfill placed from _____ ft. to _____ ft. Material _____
Gravel placed from _____ ft. to _____ ft. Size of gravel _____

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	6	+2	58	250	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:	4	-5	300		☐	☒	☒	☐
					☐	☐	☐	☐

Final location of shoe(s) 58

(7) PERFORATIONS/SCREENS:
☒ Perforations Method saw
☐ Screens Type _____ Material _____

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
140	300	6	120	1/8	4	☐	☒
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
6gpm		298	1 hr.

Temperature of Water 57 Depth Artesian Flow Found _____
Was a water analysis done? ☐ Yes By whom _____
Did any strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other _____
Depth of strata: _____

(9) LOCATION OF WELL by legal description:
County Jackson Latitude _____ Longitude _____
Township 38S N or S. Range 1W E or W. WM.
Section 9c _____ ¼ _____ ¼
Tax Lot 1300 Lot _____ Block _____ Subdivision _____
Street Address of Well (or nearest address) _____
same as #1

(10) STATIC WATER LEVEL:
20 ft. below land surface. Date 12/4/92
Artesian pressure _____ lb. per square inch. Date _____

(11) WATER BEARING ZONES:
Depth at which water was first found 140

From	To	Estimated Flow Rate	SWL
140	150	6	20

(12) WELL LOG:
Ground elevation _____

Material	From	To	SWL
Top soil, brown	0	4	
Clay, yellow	4	20	
Claystone, lt gray	20	52	
Claystone, dk gray	52	140	
Rock, gray	140	300	20
PULLED EXISTING CASING AND RE- CONSTRUCTED THE WELL.			

Date started 12/3/92 Completed 12/4/92

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.
WWC Number 1432
Signed Frank Cornelia Date 12/4/92

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.
WWC Number 679
Signed John Studebaker Date 12/16/92

ORIGINAL & FIRST COPY - WATER RESOURCES DEPARTMENT SECOND COPY - CONSTRUCTOR THIRD COPY - CUSTOMER 9809C 10/91