JACK 30224

STATE OF OREGON
WATER WELL REPORT
(as required by ORS 537.765)

STUDEBAKER DRILLING, INC.
1133 S. Riverside #16
Medford, Oregon 97501

RECEIVED
JAN 19 1993
WATER RESOURCES DEPT.
SALEM, OREGON

37S/2W/16d

(START CARD) # 44993

(1) OWNER: Well Number
Name Shawn & Ed Kellum
Address 1631 Angelcrest Dr.
City Medford State OR Zip 97504

(2) TYPE OF WORK:
XX New Well ☐ Deepen ☐ Recondition ☐ Abandon

(3) DRILL METHOD:
XX Rotary Air ☐ Rotary Mud ☐ Cable
☐ Other

(4) PROPOSED USE:
XX Domestic ☐ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval ☐ Yes ☒ No Depth of Completed Well 160 ft.
Explosives used ☐ Yes XX No Type Amount

HOLE Diameter	From	To	SEAL Material	From	To	Amount sacks or pounds
10	0	130	Bentonite	0	25	7 sacks
			chips	25	35	3 sacks
6	130	160				

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
XX Other poured
Backfill placed from ft. to ft. Material
Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	6	+2	130	250	☒	☐	☒	☐
Liner:	4	100	160		☐	☒	☒	☐

Final location of shoe(s) 130

(7) PERFORATIONS/SCREENS:
☒ Perforations Method saw
☐ Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
100	160	6	90	1/8=	4"	☐	XX

(8) WELL TESTS: Minimum testing time is 1 hour
☐ Pump ☐ Bailer XX Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
35		158	1 hr.

Temperature of Water 57 Depth Artesian Flow Found
Was a water analysis done? ☐ Yes By whom
Did any strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other
Depth of strata:

(9) LOCATION OF WELL by legal description:
County Jackson Latitude Longitude
Township #37S N or S. Range 2W E or W. WM.
Section 16D ¼ ¼
Tax Lot 912 Lot Block Subdivision
Street Address of Well (or nearest address) 2380 Jerry Rd., Central Point, Oregon

(10) STATIC WATER LEVEL:
17 ft. below land surface. Date 12-16-92
Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:
Depth at which water was first found 117'

From	To	Estimated Flow Rate	SWL
117	123	15	17
133	142	20	17

(12) WELL LOG:
Ground elevation

Material	From	To	SWL
Top soil, brown	0	5	
Clay, sandy, yellow, brown	5	20	
Claystone, sticky, gray	20	34	
Granite, decomposed, brown/gray	34	81	
Claystone, sticky, gray	81	160	17

Date started 12-13-92 Completed 12-16-92

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.
WWC Number 1432
Signed Frank Canada Date 12-16-92

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.
WWC Number 679
Signed John Studebaker Date 1-12-93

ORIGINAL & FIRST COPY - WATER RESOURCES DEPARTMENT SECOND COPY - CONSTRUCTOR THIRD COPY - CUSTOMER 9809C 10/91