DEC 1 3 1993

RECEIVED

365/4	Lw/36
<i></i>	
	/

. STATE OF OREGON NATER WELL REPORT (as required by ORS 537.765)	32916
STATE OF OREGON	TACK

WATER WEI (as required by		1 329/	6	DEG TO	1993	(START CARD) #	5728	7		
(1) OWNED.		W. II W. I		SALEMA	REGO	WELL by legal	dogou!			
(1) OWNER: Name Gib Hi	iao	Well Number								
Address 2221 I				County Jackson Latitude Longitude Township 36S N or S. Range 4W E or W. WM.						
			7:- 07505							
City Gold I		State OR	Zip 97525							
(2) TYPE OF W		- -				_LotBlock_				
XX New Well	*	Recondition	Abandon	Street Addre	ess of W	ell (or nearest address).	_sam	e as	(1)	
(3) DRILL MET										
XX Rotary Air	Rotary Mud	L Cable	•			ER LEVEL:				
Other						elow land surface.				
(4) PROPOSED				Artesian pre	essure	lb. per squ	are inch.	. Date		
		Industrial Irri	igation	(11) WATER	R BEA	RING ZONES:				
	Injection [
(5) BORE HOLI				Depth at which	water w	as first found	<u> 52</u>			
		No Depth of Com								·
Explosives used	Yes X No Ty	ype A	Amount	From		То		ated Flow	/ Rate	SWL
HOLE		SEAL	Amount	52		91		3½		45
Diameter From T		al From To								
10 0 3	38 Bento	nite 0 25	8 sacks							
	Chip	s 25 38								
6 38 24	0			(12) WELL	I OG:					
				(12) (12)	LOG.	Ground elevati	on			
How was seal placed:	Method A	□в □с □	р 🗆 Е							
Other po						Material		From	То	SWL
		ft. Material	*	Soil	· · · · · · · · · · · · · · · · · · ·	Br	own	0	7	
		ft. Size of grave		1 1		composed Br		1	12	
(6) CASING/LIN						Gr Gr		12	53	
		Gauge Steel Plastic	Welded Threaded			basalt ribs		12		
Casing: 6 +			xx	J CLAILL C	V./		ack	53	240	4.5
Casing							acr.	ررر	240	7
T: /s	80 IÓŌ						_ +. J	£ 4		
Liner: 4	00 100					ر الماريخ الم	<u>- * . 다 원.</u>	==== ## c#		
	(s)38		<u> </u>							
Final location of shoe	· /	TENIC.				E .	<u>; ; 1</u>	193		
						1/01	(4) -	- \	71.	
Perforations	-					yîi 1 A	اللاسيات			
☐ Screens	Type	Mater	ial			WATER H	<u> </u>			
From To	Slot	Tele/pipe Diameter size	Continue I to an			SUL SUL	Ele.			-
rrom 10	size Number	Diameter size	Casing Liner			· = 114/2				<u> </u>
										
) 										
				Well y	was	witched				
			🖳 🛶 🔛							
			. Ц. Д							
(8) WELL TEST	S: Minimun	testing time is 1	hour	L				L		
(- /		-	Flowing	Date started	10	/27/93 Com	pleted _	10/27	<u>7/93</u>	
Pump [☐ Bailer	X Air	Artesian			l Constructor Certifica				
Yield gal/min	Drawdown	Drill stem at	Time			ork I performed on the				
	Drawdown	-	rane			mpliance with Oregon w				
3½		239	1 hr.	used and inform	nation re	ported above are true to) my besi	. knowied	ige and o	ener.
								WWC N	umber 💃	<u> 579</u>
				Signed				Date		
						Constructor Certification	_			
Temperature of Water	57	Depth Artesian Flow	Found	1 .		ty for the construction, a		, or abanc	lonment '	work per-
Was a water analysis done? Yes By whom				formed on this	well duri	ng the construction dates	reported	above. A	ll work p	erformed
Did any strata contain water not suitable for intended use? Too little				during this time is in compliance with Oregon well construction standards. This report						
		Colored Dother _				knowledge and belief.		WWCN	Number	679
		Colored — Other —	•	Signed	lohu	Studibole		Date 11	1991	93
Depui oi suala.	<u> </u>			DIENCU	,- , , ' \	C		بليل بالد		