

STATE OF OREGON
WATER WELL REPORT
(as required by ORS 537.765)

RECEIVED

JUN 10 1994

(START CARD) # L5808

(1) OWNER:

Name Byron Farrington
Address 5321 Coaleigh Rd.
City Burke Falls State OR Zip 97528

Well Number SALEM

WATER RES

(2) TYPE OF WORK:

☒ New Well ☐ Deepen ☐ Recondition ☐ Abandon

(3) DRILL METHOD:

☒ Rotary Air ☐ Rotary Mud ☐ Cable
☐ Other

(4) PROPOSED USE:

☒ Domestic ☐ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other

(5) BORE HOLE CONSTRUCTION:

Special Construction approval ☐ Yes ☒ No Depth of Completed Well 300 ft.
Explosives used ☐ Yes ☒ No Type _____ Amount _____

HOLE		SEAL		Amount	
Diameter	From To	Material	From To	sacks or pounds	
10"	0 18	Bentonite	0 18	10 sacks	
6"	18 300				

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E

☒ Other packed

Backfill placed from _____ ft. to _____ ft. Material _____

Gravel placed from _____ ft. to _____ ft. Size of gravel _____

(6) CASING/LINER:

Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing: 6"	0	19	250	☒	☐	☒	☐
Liner:				☐	☐	☐	☐

Final location of shoe(s) 19'

(7) PERFORATIONS/SCREENS:

☐ Perforations Method _____
☐ Screens Type _____ Material _____

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
2		300	1 hr.

Temperature of Water 50° Depth Artesian Flow Found _____

Was a water analysis done? ☐ Yes By whom _____

Did any strata contain water not suitable for intended use? ☐ Too little

☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other _____

Depth of strata: _____

(9) LOCATION OF WELL by legal description:

County Jackson Latitude _____ Longitude _____
Township 34 N or S Range 2 E or W WM.
Section 29 1/4 _____ 1/4 _____
Tax Lot 4301 Lot _____ Block _____ Subdivision _____

Street Address of Well (or nearest address) _____

5321 Coaleigh Rd.

(10) STATIC WATER LEVEL:

25 ft. below land surface. Date 5/19/94
Artesian pressure _____ lb. per square inch. Date _____

(11) WATER BEARING ZONES:

Depth at which water was first found 80'

From	To	Estimated Flow Rate	SWL
80'	82	2	25

(12) WELL LOG:

Ground elevation _____

Material	From	To	SWL
Clay + gravel	0	11	
Black bedrock	11	300	25

Date started 5/16/94 Completed 5/19/94

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.

Signed Dan J. Disher WWC Number 1535
Date 5/30/94

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.

Signed Dan J. Disher WWC Number 1379
Date 5/30/94