NOTICE TO WATER WELL CONTRACTOR
The original and first copy of this report are to be filed with the STATE ENGINEER, SALEM, OREGON 97310 within 30 days from the date of well completion.

RECEIVED APR 14 1965 STATE ENGINEER SALEM, OREGON

JACK 3501

WATER WELL REPORT
STATE OF OREGON
(Please type or print)

State Well No. 35/2w-13bc

State Permit No. G 6068

(1) OWNER:

Name Gervis G. & E. Charlotte Esbell

Address General Delivery
Gold Hill, Oregon

(2) LOCATION OF WELL:

County Jackson Driller's well number

¼ ¼ Section 23 T. 35S R. 2W W.M.

Bearing and distance from section or subdivision corner
Parcel # 8144-31
Valley Home Acres

(3) TYPE OF WORK (check):

New Well ☒ Deepening ☐ Reconditioning ☐ Abandon ☐
If abandonment, describe material and procedure in Item 12.

(4) PROPOSED USE (check):

Domestic ☒ Industrial ☐ Municipal ☐
Irrigation ☐ Test Well ☐ Other ☐

(5) TYPE OF WELL:

Rotary ☒ Driven ☐
Cable ☐ Jetted ☐
Dug ☐ Bored ☐

(6) CASING INSTALLED: Threaded ☐ Welded ☒

6" Diam. from 0 ft. to 21 ft. Gage 250
" Diam. from ft. to ft. Gage
" Diam. from ft. to ft. Gage

(7) PERFORATIONS: Perforated? ☐ Yes ☒ No

Type of perforator used
Size of perforations in. by in.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

(8) SCREENS: Well screen installed? ☐ Yes ☒ No

Manufacturer's Name
Type Model No.
Diam. Slot size Set from ft. to ft.
Diam. Slot size Set from ft. to ft.

(9) CONSTRUCTION:

Well seal—Material used in seal Bentonite
Depth of seal 21 ft. Was a packer used? no
Diameter of well bore to bottom of seal 8 in.
Were any loose strata cemented off? ☐ Yes ☒ No Depth
Was a drive shoe used? ☐ Yes ☒ No
Was well gravel packed? ☐ Yes ☒ No Size of gravel:
Gravel placed from ft. to ft.
Did any strata contain unusuable water? ☐ Yes ☒ No
Type of water? depth of strata
Method of sealing strata off

(10) WATER LEVELS:

Static level 15 ft. below land surface Date April 12
Artesian pressure lbs. per square inch Date

(11) WELL TESTS: Drawdown is amount water level is lowered below static level

Was a pump test made? ☐ Yes ☒ No If yes, by whom?
Yield: gal./min. with ft. drawdown after hrs.
" " " "
" " " "
Bailer test 100 gal./min. with 22 ft. drawdown after 1 hrs.
Artesian flow g.p.m. Date
Temperature of water 57 Was a chemical analysis made? ☐ Yes ☒ No

(12) WELL LOG: Diameter of well below casing 6

Depth drilled 135 ft. Depth of completed well 135 ft.

Formation: *Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.*

MATERIAL	FROM	TO
Soil & clay--yellow	0	12
Sandstone--blue	12	135

Work started April 10 1965. Completed April 12 1965
Date well drilling machine moved off of well April 12 1965

(13) PUMP:

Manufacturer's Name
Type: H.P.

Water Well Contractor's Certification:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME GRIBBLE & MILKOWSKI (Person, firm or corporation) (Type or print)

Address Rt. 2 Box 483, Gold Hill, Oregon

Drilling Machine Operator's License No. 87

[Signed] Virgil Gribble (Water Well Contractor)

Contractor's License No. 73 Date April 13, 1965

(USE ADDITIONAL SHEETS IF NECESSARY)