ORIGINAL
File Original and Duplicate with the STATE ENGINEER, SALEM, OREGON

JACK 35227

RECEIVED SEP 11 1957 STATE ENGINEER SALEM, OREGON

WATER WELL REPORT
STATE OF OREGON

State Well No. 36/1W-1M(1)

State Permit No. 6659

G767

(1) OWNER:
Name Andy E. Allen
Address 1176 S. Hugo Rd.
Medford, Ore.

(2) LOCATION OF WELL:
County Jackson Owner's number, if any—
¼ ¼ Section T. R. W.M.
Bearing and distance from section or subdivision corner E. ½ of Lots 4 & 5 EAGLE Heights Fruit FARMS, + Lot #18, EAGLE Heights Fruit FARMS. Filed in Plat Book #1, Pages 43 + 45 Records JACKSON County ORe 450' W. of E. Boundary + 300 Ft S. of N. Boundary.

TYPE OF WORK (check):
New Well ☒ Deepening ☐ Reconditioning ☐ Abandon ☐
If abandonment, describe material and procedure in Item 11.

(4) PROPOSED USE (check):
Domestic ☒ Industrial ☐ Municipal ☐
Irrigation ☐ Test Well ☐ Other ☐

(5) TYPE OF WELL:
Rotary ☐ Driven ☐
Cable ☒ Jetted ☐
Dug ☐ Bored ☐

(6) CASING INSTALLED: Threaded ☐ Welded ☒
" Diam. from ft. to ft. Gage
" Diam. from ft. to ft. Gage
" Diam. from ft. to ft. Gage

(7) PERFORATIONS: Perforated? ☐ Yes ☒ No
Type of perforator used
SIZE of perforations in. by in.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

SCREENS: Well screen installed ☐ Yes ☒ No
Manufacturer's Name
Type Model No.
Diam. Slot size Set from ft. to ft.
Diam. Slot size Set from ft. to ft.

CONSTRUCTION:
Was well gravel packed? ☐ Yes ☒ No Size of gravel:
Gravel placed from ft. to ft.
Was a surface seal provided? ☐ Yes ☒ No To what depth? ft.
Material used in seal
Did any strata contain unusable water? ☐ Yes ☒ No
Type of water? Depth of strata
Method of sealing strata off

(10) WATER LEVELS:
Static level 15 ft. below land surface Date 7 Sept. 57
Artesian pressure lbs. per square inch Date

Log Accepted by:
[Signed] Andy E. Allen (Owner) Date 8 Sept., 1957

(11) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? ☐ Yes ☒ No If yes, by whom?
Yield: gal./min. with ft. drawdown after hrs.
" " " "
" " " "
Bailer test 60 gal./min. with 25 ft. drawdown after 1½ hrs.
Artesian flow g.p.m. Date
Temperature of water Was a chemical analysis made? ☐ Yes ☒ No

(12) WELL LOG: Diameter of well 6 inches.
Depth drilled 80 ft. Depth of completed well 80 ft.
Formation: *Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.*

MATERIAL	FROM	TO
Top Soil	0	5'
Yellow CLAY	5'	18'
Blue Shale	18'	80'

Work started 7 Sept 1957 Completed 8 Sept 1957

(13) PUMP:
Manufacturer's Name
Type: H.P.

Well Driller's Statement:
This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.
NAME Rogue Valley Drilling Co. (Person, firm, or corporation) (Type or print)
Address 885 Shafer Lane, Medford, Ore.
Driller's well number
[Signed] Jack N. Butteker (Well Driller)
License No. 172 Date 8 Sept., 1957

(USE ADDITIONAL SHEETS IF NECESSARY)