

RECEIVED

STATE OF OREGON
WATER SUPPLY WELL REPORT WATER RESOURCES DEPT.
(as required by ORS 537.765) SALEM, OREGON
Instructions for completing this report are on the last page of this form

Jack
51434

Well Number: _____

Name Muriel Anderson
Address 608 East Jackson #2

Address 600 East
City Medford

State OR Zip 97504

☒ New Well ☐ Deepening ☐ Alteration (repair/recondition) ☐ Abandonment

☒ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger
☐ Other _____

☒ Domestic ☐ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☐ Livestock ☐ Other _____

Special Construction approval ☐ Yes ☒ No Depth of Completed Well 190 ft.
Explosives used ☐ Yes ☒ No Type _____ Amount _____

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E

☒ Other poured dry

Backfill placed from _____ ft. to _____ ft. Material _____

Gravel placed from _____ ft. to _____ ft. Size of gravel _____

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing: 6		+3	19	.250	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner: 4		3	190	160	☐	☒	☒	☐
					☐	☐	☐	☐

Final location of shoe(s) 19

☒ Perforations Method **skillsaw**
☐ Screens Type _____ Material _____

From		To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
90	190	1/4"6	166				☐	☒
							☐	☐
							☐	☐
							☐	☐
							☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
---------------	----------	---------------	------

50		190	1 hr.
----	--	-----	-------

Temperature of Water **57** Depth Artesian Flow found

Was a water analysis done? ☐ Yes By whom _____

Did any strata contain water not suitable for intended use? ☐ Too little

☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other

Depth of strata:

) LOCATION OF WELL by legal description.
 County Jackson Latitude _____ Longitude _____
 Township 35S N or S. Range 2W E or W. of WM.
 Section 32 SW $\frac{1}{4}$ SE $\frac{1}{4}$
 Tax Lot 2004 Lot _____ Block _____ Subdivision _____
 Street Address of Well (or nearest address)
Tresham road

15 ft. below land surface. Date 9/1/97

Artesian pressure lb. per square inch. Date

Depth at which water was first found 37

From	To	Estimated Flow Rate	SWL
37	41	6	15
76	79	6	15
142	149	38	15

Ground elevation _____

Material	From	To	SWL
top soil	0	2	
tan clay	2	6	
grey claystone	6	37	
broken brown siltstone	37	41	15
green sandstone	41	76	
broken brown siltstone	76	79	15
coal	79	84	
grey sandstone	84	142	
broken brown siltstone	142	149	15
grey sandstone	149	190	

ASHLAND DRILLING
600 S. Pacific Hwy.
Talent, OR 97540
(503) 488-2827 772-1803

Date started **9/1/97**

Completed 9/1/97

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to my best knowledge and belief.

WWC Number 1631
Date 9-23-97

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

Signed [Signature] WWC Number 1470
Date 7-23-97