STATE OF OREGON LI.D.# ×09378 (START CARD) # 10289 6 WATER SUPPLY WELL REPORT (as required by ORS 537.765) PRINT 60-98 Instructions for completing this report are on the last page of this form (9) LOCATION OF WELL by legal description: (1) OWNER: Well Number 1009 -County JACKSON Latitude Longitude N or S Range 460 ALW 1/4 (2) TYPE OF WORK Block New Well Deepening Alteration (repair/recondition) Abandonment Street Address of Well (or nearest address) (3) DRILL METHOD: (10) STATIC WATER LEVEL: Rotary Mud ☐ Cable Auger Rotary Air ft. below land surface. Other (4) PROPOSED USE: Artesian pressure lb. per square inch. (11) WATER BEARING ZONES: Industrial Irrigation Domestic Community Other Injection Livestock Thermal (5) BORE HOLE CONSTRUCTION: Depth at which water was first found Special Construction approval Yes No Depth of Completed Well 5 ft. SWL **Estimated Flow Rate** Explosives used Yes No Type From HOLE SEAL 20 Sacks or pounds From Material From Diameter (12) WELL LOG: How was seal placed: Method Ground Elevation & CAped Other HOUSE SWL То From Material Material Backfill placed from ft. Size of gravel Gravel placed from ft. to (6) CASING/LINER: 18 Gauge Steel Plastic Welded Threaded  $\boxtimes$ X 26 26 15 105 Liner: Final location of shoe(s) (7) PERFORATIONS/SCREENS: Perforations Method Material Screens Tele/pipe Casing Liner From Number Diameter (8) WELLTESTS: Minimum testing time is 1 hour Completed (unbonded) Water Well Constructor Certification: Flowing I certify that the work I performed on the construction, alteration, or abandonment Pump Bailer Air Artesian of this well is in compliance with Oregon water supply well construction standards. Yield gal/min Drawdown Drill stem at Time Materials used and information reported above are true to the best of my knowledge (1 hr. and belief. WWC Number Signed Depth Artesian Flow Found Temperature of water 53 (bonded) Water Well Constructor Certification: Yes By whom I accept responsibility for the construction, alteration, or abandonment work Was a water analysis done? performed on this well during the construction dates reported above. All work Did any strata contain water not suitable for intended use? performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief. Salty Muddy Odor Colored Other Depth of strata: