STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)
Instructions for completing this report are on the last page of this form.

Jack 55327

WELL I.D. # L 33435
START CARD # 85265

(1) LAND OWNER Well Number _____
Name Timothy L. Johnson
Address 1298 Garnet ST
City Montbo State Ca Zip 92359

(2) TYPE OF WORK
☒ New Well ☐ Deepening ☐ Alteration (repair/recondition) ☐ Abandonment

(3) DRILL METHOD:
☒ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger
☐ Other _____

(4) PROPOSED USE:
☒ Domestic ☐ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☐ Livestock ☐ Other _____

(5) BORE HOLE CONSTRUCTION:
Special Construction approval ☐ Yes ☒ No Depth of Completed Well 362 ft.
Explosives used ☐ Yes ☒ No Type _____ Amount _____

HOLE Diameter	From	To	SEAL Material	From	To	Sacks or pounds
10	0	9	Cement	0	9	4
10	9	38	Bentonite	9	38	11
6	38	362				

How was seal placed: Method ☐ A ☐ B ☒ C ☐ D ☐ E
☐ Other _____
Backfill placed from _____ ft. to _____ ft. Material _____
Gravel placed from _____ ft. to _____ ft. Size of gravel _____

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	6	1 1/2	38 1/2	1/4	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:	4	0	362	1/4	☐	☒	☐	☐
					☐	☐	☐	☐

Drive Shoe used ☐ Inside ☒ Outside ☐ None
Final location of shoe(s) 38 1/2

(7) PERFORATIONS/SCREENS:
☒ Perforations Method Saw
☐ Screens Type Slot Material PVC

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
280	340	8"	70	1/8	4	☐	☒
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
30		361	1 hr.

Temperature of water 53 Depth Artesian Flow Found _____
Was a water analysis done? ☐ Yes By whom _____
Did any strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other _____
Depth of strata: _____

(9) LOCATION OF WELL by legal description:
County Jackson Latitude _____ Longitude _____
Township 38 N or S Range 3 E or W WM.
Section 21 SW 1/4 NE 1/4
Tax Lot 209 Lot 03 Block _____ Subdivision _____
Street Address of Well (or nearest address) 1467 China Gulch Rd. Jacksonville, OR

(10) STATIC WATER LEVEL:
93 ft. below land surface. Date 3-20-02
Artesian pressure _____ lb. per square inch Date _____

(11) WATER BEARING ZONES:
Depth at which water was first found 102

From	To	Estimated Flow Rate	SWL
102	105	3	93
270	352	27	93

(12) WELL LOG:
Ground Elevation _____

Material	From	To	SWL
Clay Brn	0	6	
Rock weathered	6	19	
Clay Brn	19	24	
Rock Black	24	102	
" Frac. Black	102	105	
" Frac. Black	105	362	93

RECEIVED APR 11 2002 WATER RESOURCES DEPT SALEM, OREGON

RECEIVED APR 30 2003 WATER RESOURCES DEPT. SALEM, OREGON

Date started 1-18-02 Completed 3-20-02

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.
WWC Number _____
Signed _____ Date _____

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.
WWC Number 679
Signed John Studebaker Date 4-2-02

ORIGINAL – WATER RESOURCES DEPARTMENT FIRST COPY – CONSTRUCTOR SECOND COPY – CUSTOMER