Corrected by WRD staff

JACK 56023
56023

WELL I.D.# 56945

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)

(START CARD) # 143786

Instructions for completing this report are on the last page of this form.

(1) OWNER: Well Number

Name MARTINA COFFMAN-(THOL)
Address 680 BRENTWOOD DRIVE
City EAGLE POINT State OR Zip 97524

(2) TYPE OF WORK

[X] New Well [ ] Deepening [ ] Alteration (repair/recondition) [ ] Abandonment

(3) DRILL METHOD:

[ ] Rotary Air [ ] Rotary Mud [X] Cable [ ] Auger
[ ] Other

(4) PROPOSED USE:

[X] Domestic [ ] Community [ ] Industrial [ ] Irrigation
[ ] Thermal [ ] Injection [ ] Livestock [ ] Other

(5) BORE HOLE CONSTRUCTION:

Special Construction approval [ ] Yes [ ] No Depth of Completed Well 198 ft.
Explosives used [ ] Yes [ ] No Type Amount

HOLE Diameter	From	To	SEAL Material	From	To	Sacks or pounds
10"	0	26	BENTONITE	0	26	20 Sacks
6"	26'	198'				

How was seal placed: Method [ ] A [ ] B [ ] C [ ] D [ ] E
[X] Other BENTONITE
Backfill placed from ft. to ft. Material
Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	6"	+1	35'	.250	[X]	[ ]	[X]	[ ]
					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
Liner:					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]

Final location of shoe(s)

(7) PERFORATIONS/SCREENS:

[X] Perforations Method SAW
[ ] Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
100'	198	1/8	30	4"		[ ]	[X]
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]

(8) WELL TESTS: Minimum testing time is 1 hour

[ ] Pump [X] Bailer [ ] Air [ ] Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
9gpm	190'		1 hr.

Temperature of water 52° Depth Artesian Flow Found
Was a water analysis done? [ ] Yes By whom
Did any strata contain water not suitable for intended use? [ ] Too little
[ ] Salty [ ] Muddy [ ] Odor [ ] Colored [ ] Other
Depth of strata:

(9) LOCATION OF WELL by legal description:

County JACKSON Latitude Longitude
Township 35 N or S Range 1W E or W. WM.
Section ~~05~~ 33 NE 1/4 SW 1/4
Tax Lot 205 Lot Block Subdivision
Street Address of Well (or nearest address) 680 BRENTWOOD DRIVE EAGLE POINT OR 97524

(10) STATIC WATER LEVEL:

100 ft. below land surface. Date March 29, 03
Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:

Depth at which water was first found 165'

From	To	Estimated Flow Rate	SWL
165'	168'	9gpm	100

(12) WELL LOG:

Ground Elevation

Material	From	To	SWL
SOIL (BROWN)	0	5	
CLAYSTONE (YELLOW)	5'	17'	
CLAYSTONE (GREEN)	17'	26'	
CLAYSTONE (BLUE)	26'	35'	
ROCK (BLACK)	35'	165'	
CLAYSTONE (BLUE)	165'	198'	100

RECEIVED
APR 09 2003

RECEIVED
MAY 22 2003
WATER RESOURCES DEPT
SALEM, OREGON

Date started March 25, 03 Completed March 29, 03

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

Signed Scott Coffman WWC Number 1705 Date March 29 03

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

Signed Jack N. Rattler WWC Number 172 Date March 29 03

ORIGINAL & FIRST COPY-WATER RESOURCES DEPARTMENT SECOND COPY-CONSTRUCTOR THIRD COPY-CUSTOMER