

Griddle Well Drilling Inc.

STATE OF OREGON WATER SUPPLY WELL REPORT

(WELL ID.)# L 08301 68251 (START CARD)# 107834 157834

Instructions for completing this report are on the last page of this form.

(1) OWNER: Well Number Name USDA Plaque River National Forest Address 338 W. 1st St P.O. Box 520 City Medford State Or Zip 97501

(2) TYPE OF WORK: [X] New Well [] Deepening [] Alteration (repair/recondition) [] Abandonment

(3) DRILL METHOD: [X] Rotary Air [] Rotary Mud [] Cable [] Auger [] Other

(4) PROPOSED USE: [X] Domestic [] Commercial [] Industrial [] Irrigation [] Thermal [] Injection [] Livestock [] Other

(5) BORE HOLE CONSTRUCTION: Special Construction approval [] Yes [X] No Depth of Completed Well 300 ft. Explosives used [] Yes [X] No Type Amount

Table with columns: HOLE (Diameter, From, To), SEAL (Material, From, To), and Sacks or pounds. Row 1: 6 inch, 0 to 30, 39, 300.

How was seal placed: Method [] A [] B [] C [] D [] E [X] Other (poured dry) Backfill placed from 0 ft. to 0 ft. Material Gravel placed from 0 ft. to 0 ft. Size of gravel

(6) CASING/LINER: Table with columns: Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded. Casing: 6 inch, 0 to 100, 270, [X]. Liner: 4 inch, 0 to 200, 232, [X].

(7) PERFORATIONS/SCREENS: [X] Perforations Method: In the air [] Screens Type Material

Table for Perforations/Screens with columns: From, To, Slot size, Number, Diameter, Telephone size, Casing, Liner.

(8) WELL TESTS: Minimum testing time is 1 hour. [] Pump [] Boiler [X] Air [] Flowing [] Artesian. Yield gallons Per minute Drill stops at 200 These 1 hr.

Temperature of water 45 Depth Artesian Flow Found Was a water analysis done? [] Yes By whom Did any strata contain water not suitable for intended use? [] Too little [] Salty [] Muddy [] Odor [] Colored [] Other Depth of strata:

(9) LOCATION OF WELL by legal description: County Jackson Latitude 42 46.98 Longitude W122 29.38 Township 32 S S Range 3 E E WM Section 20 SW 1/4 SW 1/4 Tax Lot USFS Lot Block Subdivision Street Address of Well (or nearest address) 47201 Hwy 62 Prospect Or 97536

(10) STATIC WATER LEVEL: 88' ft. below land surface. Date 11/21/03 Artesian pressure ft. per square inch. Date

(11) WATER BEARING ZONES: Depth at which water was first found 163

Table with columns: From, To, Estimated Flow Rate, SWL. Row 1: 163, 168, 10, 88. Row 2: 225, 245, 30+, 88.

(12) WELL LOG: Ground Elevation

Table with columns: Material, From, To, SWL. Yellow Pumice & boulders 0 to 11. Blue lava rock 11 to 88. Blue lava rock (shattered) 88 to 184. Gray lava rock 184 to 198. Gray lava rock (shattered) 198 to 232. Blue lava rock 232 to 300.

Well cased in from 260-300 with shattered lava rock gray - liner setting on case.

RECEIVED stamp with date FEB 26 2004 and WATER RESOURCES DEPT SALEM, OREGON. Includes RECEIVED stamp with date DEC 19 2003.

Date started 11/21/03 Completed 11/26/03 (bonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

Signed [Signature] WWC Number 1001 Date 12/12/03