TATE OF OREGON VATER SUPPLY WELL REPORT Is required by ORS 537.765)	WELLID.#L Open JJ C
astructions for completing this report are on the last page of this form. LAND OWNER Well Number	START CARD # 162744 (9) LOCATION OF WELL (legal description)
lame RIVER RUN WATER	County JACKSON Tax Lot Lot
uddress PO BOX 526 Lity State Zip SHADY COVE, OR 97539	Township 34.00S Range 1.00W WM Section 10 1/4 1/4
	Latitude Longitude 445 Hudspath Rd
2) TYPE OF WORK	Street Address / Nearest Address Page 510 SHADY COVE, OR 97539
teepening	(10) STATIC WATER LEVEL
	100 ft. below land surface. Date 4/12/2005
3) DRILL METHOD	ft. below land surface. Date
lotary air	Artesian pressure lb per square inch. Date
4) PROPOSED USE	(11) WATER BEARING ZONES
Domestic	Depth at which water was first found 310
5) BORE HOLE CONSTRUCTION Special Construction	From To Estiamated Flow Rate SWL 310 330 10 100
Depth of completed well 540 Explosives used Type Amount	(12) WELL LOG Ground Elevation
BORE HOLE SEAL , , ,	Material From To SWL
How was seal placed: Method Other Backfill placed from ft. To ft. Material	Blue Claystone 360 540
Gravel placed from ft. To ft. Size of gravel	
(6) CASING/LINER Diameter From To Gauge Material Joints Liner 4 0 540 0.188 Steel Threaded Drive Shoe used None Final Location	Date started 4/12/2005 Completed 4/12/2005
	(unbonded) Water Well Constructor Certification
(7) PERFORATIONS/SCREENS ✓ Perforations Method ☐ Screens Type HOLT AIR PERF	I certify that the work I performed on the construction, deepening, aleteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.
From To Stot Number Diam Tele-Pipe Casing/ Size Size Liner 440 500 1 300 0.125 1 Liner	WWC Number Date 5/16/2005
(8) WELL TESTS: Minimum testing time is 1 hour	Signed
Method Air Yield gal/min Drawdown Drill Stem at Time	(bonded) Water Well Constructor Certification
10 540 1	I accept responsibility for the construction, deepening, aleteration, or abandonment work
Temperature of Water 53F degrees Depth Artesian Flow Found Was a water analysis done? By whom	during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.
Was a water analysis done? By whom Did any strata contain water not suitable for intended use: Too little	
Salty Muddy Odor Colored Other Depth of strata	Signed Synthesis 5/1/00 Date 5/16/2005

RECEIVED

MAY 1 9 2005

06/16/2004