STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765 & OAR 690-205-0210)

JACK 61786

4/14/2014

WELL I.D. LABEL# L	114213
START CARD #	1022657
ORIGINAL LOG #	

(1) LAND OWNER

Owner Well I.D.

First Name JAMES & DEBBI Last Name BLODGETT

Company

Address PO BOX 990

City EAGLE POINT State OR Zip 97524

(2) TYPE OF WORK

[X] New Well [ ] Deepening [ ] Conversion [ ] Alteration (complete 2a & 10) [ ] Abandonment(complete 5a)

(2a) PRE-ALTERATION

	Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd
Casing:									

	Material	From	To	Amt	sacks/lbs
Seal:					

(3) DRILL METHOD

[X] Rotary Air [ ] Rotary Mud [ ] Cable [ ] Auger [ ] Cable Mud [ ] Reverse Rotary [ ] Other

(4) PROPOSED USE

[ ] Domestic [ ] Irrigation [X] Community [ ] Industrial/ Commericial [ ] Livestock [ ] Dewatering [ ] Thermal [ ] Injection [X] Other RESORT

(5) BORE HOLE CONSTRUCTION

Special Standard [ ] (Attach copy)

Depth of Completed Well 60.00 ft.

BORE HOLE Dia	From	To	SEAL Material	From	To	Amt	sacks/lbs
10	0	19	Bentonite Chips	0	19	20	S
6	19	42					
5	42	60					

How was seal placed: Method [ ] A [ ] B [ ] C [ ] D [ ] E

[X] Other DRY POURED

Backfill placed from ft. to ft. Material

Filter pack from ft. to ft. Material Size

Explosives used: [ ] Yes Type Amount

(5a) ABANDONMENT USING UNHYDRATED BENTONITE

Proposed Amount Actual Amount

(6) CASING/LINER

Casing	Liner	Dia	+	From	To	Gauge	Stl	Plstc	Wld	Thrd
(•)	( )	6	[X]	1.5	38.5	.250	(•)	( )	[X]	[ ]
( )	( )		[ ]				( )	( )	[ ]	[ ]
( )	( )		[ ]				( )	( )	[ ]	[ ]
( )	( )		[ ]				( )	( )	[ ]	[ ]
( )	( )		[ ]				( )	( )	[ ]	[ ]

Shoe [ ] Inside [X] Outside [ ] Other Location of shoe(s) 38.5

Temp casing [ ] Yes Dia From To

(7) PERFORATIONS/SCREENS

Perforations Method Air

Screens Type Material

Perf/ Screen	Casing/ Liner	Screen Dia	From	To	Scrn/slot width	Slot length	# of slots	Tele/ pipe size
Perf	Casing	6	26	38	.188	1	300	

(8) WELL TESTS: Minimum testing time is 1 hour

( ) Pump ( ) Bailer (•) Air ( ) Flowing Artesian

Yield gal/min	Drawdown	Drill stem/Pump depth	Duration (hr)
25		38	1.5

Temperature 50 °F Lab analysis [ ] Yes By

Water quality concerns? [ ] Yes (describe below) TDS amount

From	To	Description	Amount	Units

(9) LOCATION OF WELL (legal description)

County JACKSON Twp 36.00 S N/S Range 4.00 E E/W WM

Sec 35 1/4 of the 1/4 Tax Lot 200

Tax Map Number Lot

Lat ° ' " or 42.39323000 DMS or DD

Long ° ' " or -122.31355000 DMS or DD

( ) Street address of well (•) Nearest address

0 HWY 140 TL 200 EAGLE POINT, OR 97524

(10) STATIC WATER LEVEL

	Date	SWL(psi)	+	SWL(ft)
Existing Well / Pre-Alteration			[ ]	
Completed Well	4/9/2014		[ ]	13

Flowing Artesian? [ ] Dry Hole? [ ]

WATER BEARING ZONES Depth water was first found 26.00

SWL Date	From	To	Est Flow	SWL(psi)	+	SWL(ft)
4/9/2014	26	38	25		[ ]	13
					[ ]	
					[ ]	
					[ ]	
					[ ]	

(11) WELL LOG

Ground Elevation

Material	From	To
Brown Clay W/Boulders	0	9
Grey Basalt Hard	9	26
Grey Basalt & Red Cinders Broken	26	38
Grey Basalt Hard	38	60

Date Started 4/8/2014 Completed 4/9/2014

(unbonded) Water Well Constructor Certification

I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

License Number Date

Signed

(bonded) Water Well Constructor Certification

I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

License Number 1835 Date 4/14/2014

Signed KEVIN D GILL (E-filed)

Contact Info (optional) Clouser Drilling Inc.