

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765 & OAR 690-205-0210)

JACK 63820

6/13/2019

WELL I.D. LABEL# L 133856
START CARD # 1043044
ORIGINAL LOG #

(1) LAND OWNER
Owner Well I.D.
First Name CHRISTINA Last Name ARAPLOU
Company
Address 2557 EAST EVANS CREEK RD.
City ROGUE RIVER State OR Zip 97537

(2) TYPE OF WORK
New Well [X] Deepening [ ] Conversion [ ]
Alteration (complete 2a & 10) [ ] Abandonment(complete 5a) [ ]

(2a) PRE-ALTERATION
Casing: Dia + From To Gauge Stl Plstc Wld Thrld
Seal: Material From To Amt sacks/lbs

(3) DRILL METHOD
Rotary Air [X] Rotary Mud [ ] Cable [ ] Auger [ ] Cable Mud [ ]
Reverse Rotary [ ] Other [ ]

(4) PROPOSED USE
Domestic [X] Irrigation [ ] Community [ ]
Industrial/ Commercial [ ] Livestock [ ] Dewatering [ ]
Thermal [ ] Injection [ ] Other [ ]

(5) BORE HOLE CONSTRUCTION
Depth of Completed Well 100.00 ft.
Special Standard [ ] (Attach copy)
BORE HOLE
Dia From To Material From To Amt sacks/lbs

How was seal placed: Method [ ] A [ ] B [ ] C [ ] D [ ] E [ ]
[X] Other DRY POURED
Backfill placed from \_\_\_ ft. to \_\_\_ ft. Material \_\_\_
Filter pack from \_\_\_ ft. to \_\_\_ ft. Material \_\_\_ Size \_\_\_
Explosives used: [ ] Yes Type \_\_\_ Amount \_\_\_

(5a) ABANDONMENT USING UNHYDRATED BENTONITE
Proposed Amount Actual Amount

(6) CASING/LINER
Casing Liner Dia + From To Gauge Stl Plstc Wld Thrld
Shoe [ ] Inside [X] Outside [ ] Other Location of shoe(s) 78
Temp casing [ ] Yes Dia From + [ ] To

(7) PERFORATIONS/SCREENS
Perforations Method
Screens Type Material
Perf/ Casing/ Screen Screen Liner Dia From To Scrn/slot width Slot length # of slots Tele/ pipe size

(8) WELL TESTS: Minimum testing time is 1 hour
Pump [ ] Bailer [ ] Air [X] Flowing Artesian [ ]
Yield gal/min Drawdown Drill stem/Pump depth Duration (hr)

Temperature 55 °F Lab analysis [ ] Yes By
Water quality concerns? [ ] Yes (describe below) TDS amount 125 ppm
From To Description Amount Units

(9) LOCATION OF WELL (legal description)
County JACKSON Twp 36.00 S N/S Range 4.00 W E/W WM
Sec 3 SW 1/4 of the SW 1/4 Tax Lot 2200
Tax Map Number Lot
Lat ° ' " or 42.46456000 DMS or DD
Long ° ' " or -123.16826000 DMS or DD
[ ] Street address of well [ ] Nearest address
2557 EAST EVANS CREEK RD. ROGUE RIVER, OR 97537

(10) STATIC WATER LEVEL
Date SWL(psi) + SWL(ft)
Existing Well / Pre-Alteration
Completed Well 5/31/2019 13
Flowing Artesian? [ ] Dry Hole? [ ]

WATER BEARING ZONES
Depth water was first found 78.00
SWL Date From To Est Flow SWL(psi) + SWL(ft)
5/31/2019 78 89 40 13

(11) WELL LOG
Ground Elevation
Material From To
BROWN CLAY 0 4
BROWN DECOMPOSED GRANITE/BRK ROCK 4 18
GRAVEL/DECOMPOSED GRANITE 18 76
BROKEN WEATHERED BASALT 76 89
GRAY BASALT HARD 89 100

Date Started 5/31/2019 Completed 5/31/2019

(unbonded) Water Well Constructor Certification
I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.
License Number 1989 Date 6/10/2019
Signed GREG ELLIS (E-filed)

(bonded) Water Well Constructor Certification
I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.
License Number 1835 Date 6/10/2019
Signed KEVIN GILL (E-filed)
Contact Info (optional) CLOUSER DRILLING INC.