Duplicate - Original made out to - Bud Hoover

File Original and First Copy with the STATE ENGINEER, SALEM, OREGON

WATER WELL REPORT
STATE OF OREGON

JAK 6425

State Well No. 36/1W-28 E

State Permit No. G-1192

(1) OWNER:
Name Burl A. Clayton
Address Rt. 2, Box 227-A Medford, Oregon

(2) LOCATION OF WELL:
County Jackson Owner's number, if any—
¼ ¼ Section 28 T. 36S R. 1W W.M.
Bearing and distance from section or subdivision corner
Commencing Common to 20, 21, 28 + 29 Hence Sw. 1700 ft Hence East 150 ft.

(3) TYPE OF WORK (check):
New Well ☑ Deepening ☐ Reconditioning ☐ Abandon ☐
If abandonment, describe material and procedure in Item 11.

(4) PROPOSED USE (check):
Domestic ☑ Industrial ☐ Municipal ☐
Irrigation ☐ Test Well ☐ Other ☐

(5) TYPE OF WELL:
Rotary ☐ Driven ☐
Cable ☑ Jetted ☐
Dug ☐ Bored ☐

(6) CASING INSTALLED: Threaded ☐ Welded ☑
6" Diam. from 0 ft. to 19½ ft. Gage 1/4"
" Diam. from ft. to ft. Gage
" Diam. from ft. to ft. Gage

(7) PERFORATIONS: Perforated? ☐ Yes ☑ No
Type of perforator used
SIZE of perforations in. by in.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

(8) SCREENS: Well screen installed ☐ Yes ☑ No
Manufacturer's Name
Type Model No.
Diam. Slot size Set from ft. to ft.
Diam. Slot size Set from ft. to ft.

(9) CONSTRUCTION:
Was well gravel packed? ☐ Yes ☑ No Size of gravel:
Gravel placed from ft. to ft.
Was a surface seal provided? ☐ Yes ☐ No To what depth? ft.
Material used in seal—
Did any strata contain unusable water? ☐ Yes ☑ No
Type of water? Depth of strata
Method of sealing strata off

(10) WATER LEVELS:
Static level 9 ft. below land surface Date 10-2-58
Artesian pressure lbs. per square inch Date

Log Accepted by:
[Signed] Mrs Burl A Clayton (Owner) Date Oct 20, 1960

(11) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? ☐ Yes ☑ No If yes, by whom?
Yield: gal./min. with ft. drawdown after hrs.
" " " "
" " " "
Bailer test 30 gal./min. with 60 ft. drawdown after 3/4 hrs.
Artesian flow g.p.m. Date
Temperature of water Was a chemical analysis made? ☐ Yes ☑ No

(12) WELL LOG: Diameter of well 6 inches.
Depth drilled 92 ft. Depth of completed well 92 ft.
Formation: *Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.*

MATERIAL	FROM	TO
Soil + Gravel	1	4
Boulders + Hardpan	4	18
Green Lava	18	92

Work started Sept. 30 1958 Completed Oct. 2 1958

(13) PUMP:
Manufacturer's Name
Type: H.P.

Well Driller's Statement:
This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME Crater Well Drilling (Person, firm, or corporation) (Type or print)
Address 3061 Crater Lake Ave. Medford, Oregon
Driller's well number
[Signed] P. A. Chitwood (Well Driller)
License No. 83 Date Oct 2, 1958

(USE ADDITIONAL SHEETS IF NECESSARY)