RECEIVED

OCT - 8 1996

WATER RESOURCES DEPT.
SALEM, OREGON

STATE OF OREGON WATER WELL REPORT

(as required by ORS 537.765)

Instructions for completing this report are on the last page of this form

JOSE #3 50471

State I.D. L02355

(START CARD) # 89717

(1) OWNER: Well Number 136-96

Name Richard Miranda

Address 661 Soldier Ck. Rd.

City Grants Pass State OR. Zip 97526

(2) TYPE OF WORK

[X] New Well [ ] Deepening [ ] Alteration (repair/recondition) [ ] Abandonment

(3) DRILL METHOD:

[X] Rotary Air [ ] Rotary Mud [ ] Cable [ ] Auger

[ ] Other

(4) PROPOSED USE:

[X] Domestic [ ] Community [ ] Industrial [ ] Irrigation

[ ] Thermal [ ] Injection [ ] Livestock [ ] Other

(5) BORE HOLE CONSTRUCTION:

Special Construction approval [ ] Yes [X] No Depth of Completed Well 105 ft.

Explosives used [ ] Yes [X] No Type Amount

HOLE Diameter	From	To	SEAL Material	From	To	Sacks or pounds
10"	0	23	Cement	0	23	9 Sacks
6"	23	105	+			Bentonite
			Bentonite			1 Sack
						Cement

How was seal placed: Method [ ] A [ ] B [ ] C [ ] D [ ] E

[X] Other Poured Dry + capped with cement

Backfill placed from ft. to ft. Material

Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	6"	+1	38	.250	[X]	[ ]	[X]	[ ]
					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
Liner:					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]

Final location of shoe(s) 38

(7) PERFORATIONS/SCREENS:

[ ] Perforations Method

[ ] Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]

(8) WELL TESTS: Minimum testing time is 1 hour

[ ] Pump [ ] Bailer [X] Air [ ] Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
28	75	105	1 hr

Temperature of water 56° Depth Artesian Flow Found

Was a water analysis done? [ ] Yes By whom

Did any strata contain water not suitable for intended use? [ ] Too little

[ ] Salty [ ] Muddy [ ] Odor [ ] Colored [ ] Other

Depth of strata:

(9) LOCATION OF WELL by legal description:

County Jose Latitude Longitude

Township 35 N or S Range 5 E or W. WM.

Section 19 N.W. 1/4 N.W. 1/4

Tax Lot 300 Lot Block Subdivision

Street Address of Well (or nearest address) 2540 Soldier Ck. Rd. Grants Pass, OR.

(10) STATIC WATER LEVEL:

30 ft. below land surface. Date 9-19-96

Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:

Depth at which water was first found 40

From	To	Estimated Flow Rate	SWL
40	105	28	30

(12) WELL LOG:

Ground Elevation

Material	From	To	SWL
Brown clay granit + gravel	0	17	
Gray clay + granit	17	25	
tombstone granit fractured	25	63	30
tombstone granit	63	105	30

Date started 9-19-96 Completed 9-19-96

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

WWC Number

Signed Date

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

WWC Number 260

Signed Date 10/1/96

ORIGINAL & FIRST COPY WATER RESOURCES DEPARTMENT, SECOND COPY CONSTRUCTOR, THIRD COPY CUSTOMER