

jose
50840

RECEIVED

FILED # L12064

MAY 30 1937

(START CARD) # 90890

Instructions for completing this report are on the last page of this form.

~~WATER RESOURCES DEPT~~

S&B MOORE OF WELL by legal description:

County Joseph Latitude _____ Longitude _____
Township 34 N or S Range 06 E or W. WM.
Section 28 SW 1/4 NW 1/4
Tax Lot 500 Lot _____ Block _____ Subdivision _____
Street Address of Well (or nearest address) 6380 Tunnel Loop Road

(10) STATIC WATER LEVEL:

6380 Tunnel Loop Road

98 ft. below land surface. Date 5-7-97

Artesian pressure lb. per square inch.

(11) WATER BEARING ZONES:

Depth at which water was first found 167

From	To	Estimated Flow Rate	SWL
167	168	2	98
388	389	1	98

(12) WELL LOG:

Ground Elevation

[illegible]

Date started 5-5-97 Completed 5-7-97

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

Signed Stacy Carter WWC Number 1659
Date 5-7-97

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

Signed Bob Quinn WWC Number 675
Date 5-8-97

(6) CASING/LINER:				Steel	Plastic	Welded	Threaded
	Diameter	From	To	Gauge			
Casing:	6	+2	147	250	☒	☐	☒
					☐	☐	☐
					☐	☐	☐
					☐	☐	☐
					☐	☐	☐
Liner:					☐	☐	☐
					☐	☐	☐
					☐	☐	☐

Final location of shoe(s) 147

(7) PERFORATIONS/SCREENS:

☐ Perforations Method _____

☐ Screens Type _____ Material _____

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
						☐	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour

☐ Pump	☐ Bailer	☒ Air	☐ Flowing Artesian
Yield gal/min	Drawdown	Drill stem at	Time
3		395	(1 hr.)

Temperature of water 54 Depth Artesian Flow Found

Was a water analysis done? ☐ Yes By whom

Did any strata contain water not suitable for intended use? ☐ Too little

☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other

Depth of strata: _____

ORIGINAL & FIRST COPY-WATER RESOURCES DEPARTMENT SECOND COPY-CONSTRUCTOR THIRD COPY-CUSTOMER