

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)

WATER RESOURCES DEPT.
SALEM, OREGON

WELL I.D. # L 27898
START CARD # 102946

Instructions for completing this report are on the last page of this form.

(1) OWNER: Well Number 1051-98
Name Adrian K. Roberts trust
Address 1044 East Crow Rd.
City Merlin State OR Zip 97532

(2) TYPE OF WORK
☒ New Well ☐ Deepening ☐ Alteration (repair/recondition) ☐ Abandonment

(3) DRILL METHOD:
☒ Rotary Air ☐ Rotary Mud ☐ Cable ☐ Auger
☐ Other

(4) PROPOSED USE:
☒ Domestic ☐ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☐ Livestock ☐ Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval ☐ Yes ☒ No Depth of Completed Well 232 ft.
Explosives used ☐ Yes ☒ No Type _____ Amount _____

HOLE			SEAL			
Diameter	From	To	Material	From	To	Sacks or pounds
10"	0	23	Cement	0	23	10 Sacks
6"	23	232	Bentonite			2 Sacks
			Cement			

How was seal placed: Method ☐ A ☐ B ☐ C ☐ D ☐ E
☒ Other Poured dry + capped with cement
Backfill placed from _____ ft. to _____ ft. Material _____
Gravel placed from _____ ft. to _____ ft. Size of gravel _____

(6) CASING/LINER:

Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing: 6"	+1	151	250	☒	☐	☒	☐
Liner:				☐	☐	☐	☐

Final location of shoe(s) 151

(7) PERFORATIONS/SCREENS:

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
						☐	☐
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour

Pump	Bailer	Air	Flowing
Yield gal/min	Drawdown	Drill stem at	Artesian
100+	162	232	Time 1 hr.

Temperature of water 56° Depth Artesian Flow Found _____
Was a water analysis done? ☐ Yes By whom _____
Did any strata contain water not suitable for intended use? ☐ Too little
☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other _____
Depth of strata: _____

(9) LOCATION OF WELL by legal description:
County Jose Latitude _____ Longitude _____
Township 35 N or S Range 6 E or W WM.
Section 7 SE 1/4 SE 1/4
Tax Lot 1600 Lot _____ Block _____ Subdivision _____
Street Address of Well (or nearest address) 1044 East Crow Rd. Merlin OR.

(10) STATIC WATER LEVEL:
70 ft. below land surface. Date 12-29-98
Artesian pressure _____ lb. per square inch. Date _____

(11) WATER BEARING ZONES:
Depth at which water was first found 145'

From	To	Estimated Flow Rate	SWL
151	232	100+	70

(12) WELL LOG:
Ground Elevation _____

Material	From	To	SWL
Crushed gravel and Bricks	0	3	
Brown clay + granite	3	22	
Brown clay	22	54	
Brown clay + granite	54	72	
Brown clay + some gravel	72	130	
gray granite	130	230	70
Tomb stone granit	230	232	70

Date started 12-28-98 Completed 12-29-98

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

Signed _____ WWC Number _____ Date _____

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.
Signed Charles E. With WWC Number 260 Date _____