JOSE
52482

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765)
Instructions for completing this report are on the last page of this form.

WELL I.D. # L 27899
START CARD # 102954

(1) OWNER: Well Number 1052-98
Name John + Michele Martin
Address P.O. Box 6
City Merlin State OR Zip 97532

(2) TYPE OF WORK
[X] New Well [ ] Deepening [ ] Alteration (repair/recondition) [ ] Abandonment

(3) DRILL METHOD:
[X] Rotary Air [ ] Rotary Mud [ ] Cable [ ] Auger
[ ] Other

(4) PROPOSED USE:
[X] Domestic [ ] Community [ ] Industrial [ ] Irrigation
[ ] Thermal [ ] Injection [ ] Livestock [ ] Other

(5) BORE HOLE CONSTRUCTION:
Special Construction approval [ ] Yes [X] No Depth of Completed Well 65 ft.
Explosives used [ ] Yes [X] No Type Amount

HOLE Diameter	From	To	SEAL Material	From	To	Sacks or pounds
10"	0	18	Cement	0	18	9½ Sacks
6"	18	65	+			Bentonite
			Bentonite			1 Sack
						Cement

How was seal placed: Method [ ] A [ ] B [ ] C [ ] D [ ] E
[X] Other Poured dry + Capped with Cement
Backfill placed from ft. to ft. Material
Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	6"	+1	48½	250	[X]	[ ]	[X]	[ ]
					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]
Liner:					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]

Final location of shoe(s) 48½

(7) PERFORATIONS/SCREENS:
[ ] Perforations Method
[ ] Screens Type Material

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]

(8) WELL TESTS: Minimum testing time is 1 hour
[ ] Pump [ ] Bailer [X] Air [ ] Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time
15	56½	65	1 hr.

Temperature of water 58° Depth Artesian Flow Found
Was a water analysis done? [X] Yes By whom G.P. Water Lab
Did any strata contain water not suitable for intended use? [ ] Too little
[ ] Salty [ ] Muddy [ ] Odor [ ] Colored [ ] Other
Depth of strata:
Salt test 88 P.P.m Salt

(9) LOCATION OF WELL by legal description:
County Jose Latitude Longitude
Township 35 N or S Range 6 E or W. WM.
Section 21 NW 1/4 NW 1/4
Tax Lot 1300 Lot #6 Block Subdivision
Street Address of Well (or nearest address) 400 Plum St
Merlin Or.

(10) STATIC WATER LEVEL:
8½ ft. below land surface. Date 12-31-98
Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES:
Depth at which water was first found 30'

From	To	Estimated Flow Rate	SWL
48½	65	15	8½

(12) WELL LOG:
Ground Elevation

Material	From	To	SWL
Brown clay Small to medium Boulders	0	30	
Fractured Black + white granite	30	65	8½

RECEIVED
JAN 14 1999
WATER RESOURCES DEPT.
SALEM, OREGON

Date started 12-30-98 Completed 12-31-98

(unbonded) Water Well Constructor Certification:
I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.
WWC Number
Signed Date

(bonded) Water Well Constructor Certification:
I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.
WWC Number 760
Signed Date

ORIGINAL & FIRST COPY-WATER RESOURCES DEPARTMENT SECOND COPY-CONSTRUCTOR THIRD COPY-CUSTOMER