

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765 & OAR 690-205-0210)

11-17-2006

\* Revised \*

WELL LABEL # L 87920

START CARD # 1000280

(1) LAND OWNER Owner Well I.D.
First Name GLENN F. Last Name WOODBURY
Company
Address 1772 ROSS LN
City MEDFORD State OR Zip 97501

(2) TYPE OF WORK [X] New Well [ ] Deepening [ ] Conversion
[ ] Alteration (repair/recondition) [ ] Abandonment

(3) DRILL METHOD
[X] Rotary Air [ ] Rotary Mud [ ] Cable [ ] Auger [ ] Cable Mud
[ ] Reverse Rotary [ ] Other

(4) PROPOSED USE [X] Domestic [ ] Irrigation [ ] Community
[X] Industrial/ Commercial [ ] Livestock [ ] Dewatering
[ ] Thermal [ ] Injection [ ] Other

(5) BORE HOLE CONSTRUCTION Special Standard [ ] Attach copy
Depth of Completed Well 240.00 ft.

Table with columns: Dia, From, To, Material, From, To, Amt, lbs. Row 1: 10, 0, 18, Bentonite Chips, 0, 18, 19, S

How was seal placed: Method [ ] A [ ] B [ ] C [ ] D [ ] E

[X] Other Dry Poured

Backfill placed from ft. to ft. Material

Filter pack from ft. to ft. Material Size

Explosives used: [ ] Yes Type Amount

(6) CASING/LINER

Table with columns: Casing, Liner, Dia, From, To, Gauge, Stl, Plstc, Wld, Thrd. Row 1: 6, 2, 18, 250, [X]

Shoe [ ] Inside [X] Outside [ ] Other Location of shoe(s) 18

Temp casing [ ] Yes Dia From To

(7) PERFORATIONS/SCREENS

Perforations Method Factory Slotted Pipe

Screens Type Material

Table with columns: Perf/ Screen, Casing/ Liner, Dia, From, To, Scrm/slot width, Slot length, # of slots, Tele/ pipe size. Row 1: 200, 220, .063, 3, 360

(8) WELL TESTS: Minimum testing time is 1 hour

Table with columns: Pump, Bailer, Air, Flowing Artesian, Yield gal/min, Drawdown, Drill stem/Pump depth, Duration (hr). Row 1: 8, 240, 1

Temperature 54 °F Lab analysis [ ] Yes By

Water quality concerns? [ ] Yes (describe below)

Table with columns: From, To, Description, Amount, Units

(9) LOCATION OF WELL (legal description)

County Josephine Twp 40.00 S N/S Range 9.00 W E/W WM
Sec 25 NW 1/4 of the NE 1/4 Tax Lot 2000
Tax Map Number Lot
Lat 0 or 42.06747700 DMS or DD
Long 0 or -123.70338900 DMS or DD
[ ] Street address of well [ ] Nearest address

469 LONE MOUNTAIN RD OBRIEN, OR 97534

(10) STATIC WATER LEVEL

Table with columns: Date, SWL(psi), SWL(ft). Row 1: 11-16-2006, 18

WATER BEARING ZONES Depth water was first found 35.

Table with columns: SWL Date, From, To, Est Flow, SWL(psi), SWL(ft). Row 1: 11-16-2006, 35, 38, 2, 18

(11) WELL LOG

Table with columns: Material, From, To. Row 1: Brown Clay Tight, 0, 4

RECEIVED

DEC 11 2006

WATER RESOURCES DEPT
SALEM, OREGON

Date Started 11-16-2006 Completed 11-16-2006

(unbonded) Water Well Constructor Certification

I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

License Number Date
Electronically Filed
Signed

(bonded) Water Well Constructor Certification

I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

License Number 1835 Date 11-17-2006
Electronically Filed
Signed KEVIN D GILL (E-filed)
Contact Info (optional) Clouser Drilling LLC