

STATE OF OREGON
WATER SUPPLY WELL REPORT
(as required by ORS 537.765 & OAR 690-205-0210)

JOSE 61328
12/31/2021

WELL I.D. LABEL# L 143878
START CARD # 1053867
ORIGINAL LOG #

(1) LAND OWNER
Owner Well I.D.
First Name BRIAN Last Name MOCKRIDGE
Company
Address PO BOX 1395
City MERLIN State OR Zip 97532

(2) TYPE OF WORK
[X] New Well [ ] Deepening [ ] Conversion
[ ] Alteration (complete 2a & 10) [ ] Abandonment (complete 5a)

(2a) PRE-ALTERATION
Dia + From To Gauge Stl Plstc Wld Thrld
Casing:
Material From To Amt sacks/lbs
Seal:

(3) DRILL METHOD
[X] Rotary Air [ ] Rotary Mud [ ] Cable [ ] Auger [ ] Cable Mud
[ ] Reverse Rotary [ ] Other

(4) PROPOSED USE
[X] Domestic [ ] Irrigation [ ] Community
[ ] Industrial/ Commercial [ ] Livestock [ ] Dewatering
[ ] Thermal [ ] Injection [ ] Other

(5) BORE HOLE CONSTRUCTION
Special Standard [ ] (Attach copy)
Depth of Completed Well 300.00 ft.
BORE HOLE
Dia From To Material From To Amt sacks/lbs

How was seal placed: Method [ ] A [ ] B [ ] C [ ] D [ ] E
[X] Other DRY POURED
Backfill placed from ft. to ft. Material
Filter pack from ft. to ft. Material Size
Explosives used: [ ] Yes Type Amount

(5a) ABANDONMENT USING UNHYDRATED BENTONITE
Proposed Amount Actual Amount

(6) CASING/LINER
Casing Liner Dia + From To Gauge Stl Plstc Wld Thrld
Shoe [ ] Inside [X] Outside [ ] Other Location of shoe(s) 105
Temp casing [ ] Yes Dia From + To

(7) PERFORATIONS/SCREENS
Perforations Method Lazer/Saw Cut
Screens Type Material
Perf/ Casing/ Screen Dia From To Scrn/slot Slot # of Tele/
width length slots pipe size

(8) WELL TESTS: Minimum testing time is 1 hour
[ ] Pump [ ] Bailer [X] Air [ ] Flowing Artesian
Yield gal/min Drawdown Drill stem/Pump depth Duration (hr)
Temperature 55 °F Lab analysis [ ] Yes By
Water quality concerns? [ ] Yes (describe below) TDS amount 111 ppm
From To Description Amount Units

(9) LOCATION OF WELL (legal description)
County JOSEPHINE Twp 35.00 S N/S Range 6.00 W E/W WM
Sec 26 NE 1/4 of the SE 1/4 Tax Lot 1900
Tax Map Number Lot
Lat " or 42.49767247 DMS or DD
Long " or -123.36770382 DMS or DD
[ ] Street address of well [X] Nearest address
MONUMENT DRIVE TL 1900 AND MERLIN RD. MERLIN, OR 97532

(10) STATIC WATER LEVEL
Date SWL(psi) + SWL(ft)
Existing Well / Pre-Alteration
Completed Well 12/15/2021 0.7 [X] 1.6
Flowing Artesian? [X] Dry Hole? [ ]

WATER BEARING ZONES
Depth water was first found 105.00
SWL Date From To Est Flow SWL(psi) + SWL(ft)
12/15/2021 105 112 5 0.7 [X] 1.6
12/15/2021 269 273 35 0.7 [X] 1.6

(11) WELL LOG
Ground Elevation
Material From To
BRN CLAY BLDRS MIXD GRVL CRSE SAND 0 7
Brown Clay Bldrs Mixed Gvl & Fine Snd 7 12
Brown White & Grey Granite 12 300
KDG 1/12/22

Date Started 9/13/2021 Completed 9/15/2021

(unbonded) Water Well Constructor Certification
I certify that the work I performed on the construction, deepening, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.
License Number 1945 Date 12/29/2021
Signed JUSTIN SPLIETHOF (E-filed)

(bonded) Water Well Constructor Certification
I accept responsibility for the construction, deepening, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.
License Number 1835 Date 12/31/2021
Signed KEVIN GILL (E-filed)
Contact Info (optional) Clouser Drilling Inc.

WATER SUPPLY WELL REPORT - Map with location identified must be attached and shall include an approximate scale and north arrow

JOSE 61328

12/31/2021

Map of Hole

