

(1) LAND OWNER

Owner Well Number _____

First Name _____ Last Name _____

Company Siskiyou Field Institute

Address PO BOX 207

City Selma State OR Zip 97538

(2) TYPE OF WELL ☒ Water Well ☐ Monitoring Well ☐ Piezometer

(3) CURRENT OBSERVED USE

☒ Domestic ☐ Community ☐ Industrial ☐ Irrigation

☐ Thermal ☐ Injection ☐ Livestock ☐ Other _____

(4) BORE HOLE CONSTRUCTION

Estimated Depth of Well 46 ft.

BORE HOLE			SEAL			
Diameter	From	To	Material	From	To	Sacks / Pounds

(5) CASING/LINER

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	6"	0	46	.250	☒	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:					☐	☐	☐	☐
					☐	☐	☐	☐

Drive Shoe used ☐ Inside ☐ Outside ☐ None

Final location of shoe(s) _____

(6) PERFORATIONS/SCREENS

☐ Perforations

☐ Screens Type _____ Material _____

From	To	Approx Slot Size	Number	Diameter	Tele/pipe size	Casing	Liner
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(7) WELL TESTS

Date _____

☐ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Drill stem at	Time

Temperature of water _____

Was a water analysis done? ☐ Yes By whom _____

(8) LOCATION OF WELL (legal description)

County Josephine County Map No 38-08-09-00-000100-00

Township 38 S N / S Range 8 W E / W WM Section 9

NE 1/4 of the SE 1/4 Tax Lot 100 Lot _____

Lat ° ' " or 42.278653 DMS or DD

Long ° ' " or -123.644989 DMS or DD

Street Address of Well (or nearest address) _____
1241 Illinois River Rd, Selma, OR 97538

(9) STATIC WATER LEVEL

14 ft. below land surface. Date 10/12/2023

Artesian pressure _____ lb. per square inch Date _____

(10) WATER BEARING ZONES

From	To	Estimated Flow Rate	SWL

(11) LITHOLOGY

Ground Elevation _____

Material	From	To
ENTERED		
OCT 16 2023		
OWRD		

Estimated date originally constructed _____

SOURCE OF DATA / INFO ☐ USGS ☒ On-Site Observation

☐ Interview _____ ☐ Other _____

OWRD staff located a currently unused domestic well on the Siskiyou
Field Institute property to be used as a potential observation well.
Lat/log coordinates collected via handheld GPS and downhole
camera used to determine construction details. Unable to attach
well ID tag at time of visit as the casing was flush with the land surface.

COMPILED BY Grayson Fish

DATE 10-16-2023