School

JOSE
6230

NOTICE TO WATER WELL CONTRACTOR
The original and first copy of this report are to be filed with the
STATE ENGINEER, SALEM, OREGON 97310 within 30 days from the date of well completion.

RECEIVED
NOV 16 1966
STATE ENGINEER
SALEM, OREGON

WATER WELL REPORT
STATE OF OREGON
(Please type or print)

SW SW
T.L. 3301

State Well No. 37/6W-12cc

State Permit No. .....

(1) OWNER:
Name Josephine County School
Address Court House Annex Grants Pass Oregon
District Drill

(2) LOCATION OF WELL:
County Josephine Driller's well number
¼ ¼ Section 12 T. 37S R. 6W W.M.
Bearing and distance from section or subdivision corner

(3) TYPE OF WORK (check):
New Well ☑ Deepening ☐ Reconditioning ☐ Abandon ☐
If abandonment, describe material and procedure in Item 12.

(4) PROPOSED USE (check):
Domestic ☐ Industrial ☐ Municipal ☑
Irrigation ☐ Test Well ☐ Other ☐

(5) TYPE OF WELL:
Rotary ☑ Driven ☐
Cable ☐ Jetted ☐
Dug ☐ Bored ☐

(6) CASING INSTALLED: Threaded ☐ Welded ☑
6" Diam. from 0 ft. to 80' ft. Gage .250
" Diam. from ft. to ft. Gage
" Diam. from ft. to ft. Gage

(7) PERFORATIONS: Perforated? ☐ Yes ☑ No
Type of perforator used
Size of perforations in. by in.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

(8) SCREENS: Well screen installed? ☐ Yes ☑ No
Manufacturer's Name
Type Model No.
Diam. Slot size Set from ft. to ft.
Diam. Slot size Set from ft. to ft.

(9) CONSTRUCTION:
Well seal—Material used in seal Cement Grout
Depth of seal 80' ft. Was a packer used? No
Diameter of well bore to bottom of seal 9 5/8 in.
Were any loose strata cemented off? ☐ Yes ☑ No Depth
Was a drive shoe used? ☑ Yes ☐ No
Was well gravel packed? ☐ Yes ☑ No Size of gravel:
Gravel placed from ft. to ft.
Did any strata contain unusable water? ☐ Yes ☑ No
Type of water? depth of strata
Method of sealing strata off

(10) WATER LEVELS:
Static level 4' ft. below land surface Date Sept 23 66
Artesian pressure lbs. per square inch Date

(11) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? ☑ Yes ☐ No If yes, by whom?
Yield: 50 gal./min. with 85 ft. drawdown after 4 hrs.
" " " "
" " " "
Bailer test gal./min. with ft. drawdown after hrs.
Artesian flow g.p.m. Date
Temperature of water 49 Was a chemical analysis made? ☐ Yes ☑ No

(12) WELL LOG: Diameter of well below casing 6"
Depth drilled 190 ft. Depth of completed well 190 ft.
Formation: *Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.*

MATERIAL	FROM	TO
Decomposed Granite & Clay	0	12
Soft Decomposed Granite	12	38
Decomposed Granite & Clay	38	76
Fractured Granite with fractures	76	190

Work started Sept 22 1966 Completed Sept 23 1966
Date well drilling machine moved off of well Sept 23 1966

(13) PUMP:
Manufacturer's Name
Type: H.P.

Water Well Contractor's Certification:
This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.
NAME R F Paquin Drilling Co (Person, firm, or corporation) (Type or print)
Address 2820 So. River Rd Grants Pass Ore
Drilling Machine Operator's License No. 422
[Signed] R F Paquin (Water Well Contractor)
Contractor's License No. 275 Date 11-15, 1966

(USE ADDITIONAL SHEETS IF NECESSARY)