

JUL 01 1991

STATE OF OREGON WATER WELL REPORT (as required by ORS 537.765)

WATER RESOURCES DEPT. SALEM, OREGON

KLAMATH 10206

41S/13E/5Cb W-26530

(START CARD) #

(1) OWNER: Name Louie Randall Address Rt. 1 Box 69A City Bonanza State OR Zip 97623

(2) TYPE OF WORK: Recondition

(3) DRILL METHOD: Cable

(4) PROPOSED USE: Irrigation

(5) BORE HOLE CONSTRUCTION: Depth of Completed Well

Table with columns: HOLE Diameter, SEAL From, To, Material, Amount sacks or pounds

How was seal placed: Method A B C D E

(6) CASING/LINER: Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded

Table for casing/liner with columns: Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded

(7) PERFORATIONS/SCREENS: Perforations Method Factory

Table for perforations/screens with columns: From, To, Slot size, Number, Diameter, Tele/pipe size, Casing, Liner

(8) WELL TESTS: Minimum testing time is 1 hour

Temperature of water, Depth Artesian Flow Found, Was a water analysis done?

(9) LOCATION OF WELL by legal description: County Klamath, Township 41S, Range 13E, Section 5, NW 1/4 SW 1/4

(10) STATIC WATER LEVEL: 10 ft. below land surface, Date 5-31-91

(11) WATER BEARING ZONES: Depth at which water was first found

Table for water bearing zones with columns: From, To, Estimated Flow Rate, SWL

(12) WELL LOG: Ground elevation

Table for well log with columns: Material, From, To, SWL

Date started 5-10-91 Completed 5-31-91

(unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards.

(bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above.