

VX

KLAM 10263

FEB 11 1992

KLAM 10263

245/6E/29ab

STATE OF OREGON

WATER WELL REPORT

(as required by ORS 537.765)

REVISED COPY

(WELL ART CARD) # 28941

(1) OWNER:

Name U.S. Forest Service-Crescent Dist.
Address P.O. Box 208
City Crescent State Or. Zip 97733

Well Number: 544-21-91

(2) TYPE OF WORK:

☒ New Well ☐ Deepen ☐ Recondition ☐ Abandon

(3) DRILL METHOD

☒ Rotary Air ☐ Rotary Mud ☐ Cable
☐ Other

(4) PROPOSED USE:

☐ Domestic ☐ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☒ Other camp ground

(5) BORE HOLE CONSTRUCTION:

Special Construction approval Yes ☐ No ☒ Depth of Completed Well 245 ft.
Explosives used ☐ Yes ☒ No ☐ Type _____ Amount _____

HOLE			SEAL			Amount sacks or pounds
Diameter	From	To	Material	From	To	
12"	-	26	type 1&2 cement	0	26	21 sks
8"	26	100				
6"	100	245				

How was seal placed: Method ☐ A ☐ B ☒ C ☐ D ☐ E

☐ Other

Backfill placed from _____ ft. to _____ ft. Material _____

Gravel placed from _____ ft. to _____ ft. Size of gravel _____

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing:	6"	1 1/2	100	.250	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner:	5"	-1	245	.188	☒	☐	☒	☐
					☐	☐	☐	☐

Final location of sheets: _____

(7) PERFORATIONS/SCREENS:

☒ Perforations Method Machine

☐ Screens Type _____ Material _____

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
225	245	1/8	190			☐	☒
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour

☐ Pump ☐ Bailer ☒ Air ☐ Flowing
☐ Artesian

Yield gal/min	Drawdown	Drill stem at	Time
37 1/2	21'	210	1 hr.
25+	20'	245	2 hr.

Temperature of water 42°

Depth Artesian Flow Found _____

Was a water analysis done? ☐ Yes By whom _____

Did any strata contain water not suitable for intended use? ☒ Too little

☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other _____

Depth of strata: _____

(9) LOCATION OF WELL by legal description:

County Klamath Latitude _____ Longitude _____
Township 24 N or S. Range 6 E ☒ W. M.
Section 29 NW 1/4 NE 1/4
Tax Lot _____ Lot 2 Block _____ Subdivision _____
Street Address of Well (or nearest address) White Fish Horse
Camp Ground, Crescent Lake, Or.

(10) STATIC WATER LEVEL:

21 ft. below land surface. Date 8-14-91
Artesian pressure _____ lb. per square inch. Date _____

(11) WATER BEARING ZONES:

Depth at which water was first found		190'	
From	To	Estimated Flow Rate	SWL
51	65	2	21
190	201	35+	21

(12) WELL LOG:

Ground elevation _____

Material	From	To	SWL
Tan Pumice	0	5	
Large Boulders	5	20	
Gray Lava	20	38	
Hard Brown Lava	38	51	
Hard Fractured Gray Bas.	51	65	21
Fractured Brown Lava	65	67	
Hard Gray Basalt	67	89	
Fractured Pink Lava	89	102	
Broken Pink Lava	102	154	
Broken Gray Lava	154	175	
Broken Gray/Brown Lava	175	190	
Coarse Red Cinder	190	201	21
Pinkish/Brown Lava	201	212	
Tan Pumice	212	218	
Red Cinder Rock/Sand/Grv.	218	238	
Gray Lava	238	245	

Date started 8-13-91 Completed 8-20-91

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.

WWC Number _____

Signed _____ Date _____

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. all work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.

WWC Number 685

Signed [Signature] Date 8-26-91

Original -
Superceded

STATE OF OREGON

WATER WELL REPORT
(as required by ORS 537.765)

AUG 28 1991

KLAM 10263

235/6E/20 dc

(START CARD) # 28941

(1) OWNER:

Well Number: 544-21-91

Name U.S. Forest Service-Crescent Dist.

Address P.O. Box 208

City Crescent State Or. Zip 97733

(2) TYPE OF WORK:

☒ New Well ☐ Deepen ☐ Recondition ☐ Abandon

(3) DRILL METHOD

☒ Rotary Air ☐ Rotary Mud ☐ Cable
☐ Other

(4) PROPOSED USE:

☐ Domestic ☐ Community ☐ Industrial ☐ Irrigation
☐ Thermal ☐ Injection ☒ Other Camp Ground

(5) BORE HOLE CONSTRUCTION:

Special Construction approval Yes ☐ No ☒ Depth of Completed Well 245 ft.
Explosives used Yes ☐ No ☒ Type _____ Amount _____

HOLE			SEAL			Amount sacks or pounds
Diameter	From	To	Material	From	To	
12"	0	26	type 1&2 cement	0	26	21 sks
8"	26	100				
6"	100	245				

How was seal placed: Method ☐ A ☐ B ☒ C ☐ D ☐ E

☐ Other _____

Backfill placed from _____ ft. to _____ ft. Material _____

Gravel placed from _____ ft. to _____ ft. Size of gravel _____

(6) CASING/LINER:

	Diameter	From	To	Gauge	Steel	Plastic	Welded	Threaded
Casing	6"	1.5	100	250	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐
Liner	5"	-1	245	188	☒	☐	☒	☐
					☐	☐	☐	☐

Final location of shoe(s) _____

(7) PERFORATIONS/SCREENS:

☒ Perforations Method Machine

☐ Screens Type _____ Material _____

From	To	Slot size	Number	Diameter	Tele/pipe size	Casing	Liner
225	245	1/8	190			☐	☒
						☐	☐
						☐	☐
						☐	☐
						☐	☐

(8) WELL TESTS: Minimum testing time is 1 hour

☐ Pump ☐ Bailer ☒ Air ☐ Flowing
☐ Artesian

Yield gal/min	Drawdown	Drill stem at	Time
25+	20'	245	2 X hr.
37.5	21'	210	1 hr.

Temperature of water 42° Depth Artesian Flow Found _____

Was a water analysis done? ☐ Yes By whom _____

Did any strata contain water not suitable for intended use? ☒ Too little

☐ Salty ☐ Muddy ☐ Odor ☐ Colored ☐ Other _____

Depth of strata: _____

(9) LOCATION OF WELL by legal description:

County Klamath Latitude _____ Longitude _____

Township 23 N or S, Range 6 E or W, WM.

Section 20 SW 1/4 SE 1/4

Tax Lot _____ Lot 2 Block _____ Subdivision _____

Street Address of Well (or nearest address) White Fish Horse
Camp Ground, Crescent Lake

(10) STATIC WATER LEVEL:

21 ft. below land surface. Date 8-14-91

Artesian pressure _____ lb. per square inch. Date _____

(11) WATER BEARING ZONES:

Depth at which water was first found 190'

From	To	Estimated Flow Rate	SWL
51	65	2	21
190	201	35+	21

(12) WELL LOG:

Ground elevation _____

Material	From	To	SWL
Tan Pumice	0	5	
Large Boulders	5	20	
Gray Lava	20	38	
Hard Brown Lava	38	51	
Hard Fractured Gray Bas.	51	65	21
Fractured Brown Lava	65	67	
Hard Gray Basalt	67	89	
Fractured Pink Lava	89	102	
Broken Pink Lava	102	154	
Broken Gray Lava	154	175	
Broken Gray/Brown Lava	175	190	
Coarse Red Cinder	190	201	21
Pinkish/Brown Lava	201	212	
Tan Pumice	212	218	
Red Cinder rock/sand/Grvl	218	238	
Gray Lava	238	245	

Date started 8-13-91 Completed 8-20-91

(unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to my best knowledge and belief.

WWC Number _____

Signed _____

Date _____

(bonded) Water Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. all work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.

WWC Number 685

Signed P.J. [Signature]

Date 8-26-91